

S. G. TORRICE COMPANY, INC. 06/09/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$384
950	7	A-S	AH	GAM2A0B42S31SEA	1514137ABV	3.5T CONV AIR HANDLER	LEAK IN COIL,NEEDS NEW COIL	\$44
2564	2	A-S	AH	TAM8C0C36V1EAA	16113TE4AY	3T AIR HANDLER	REAR OF CABINET DENTED	\$540
142	9	A-S	AH	TAM9A0A24V21DA	17171N771V	2T VS AIR HANDLER	TOP RIGHT SIDE PUSHED IN	\$950
2286	2	A-S	CL	4TXCA024BC3HCB	15472K1DBG	2T CASED COIL	TOP REAR DENTED	\$86
2586	7	A-S	CL	4TXCB006DS3HCAA	16354JRR5G	3.5-4.0T HI-EFF CSD COIL	MINOR DAMAGE TO BACK CORNER	\$223
946	7	A-S	CL	4TXCB048BC3HCB	152642X2BG	4T CASED COIL	DENTED TOP RIGHT CORNER	\$62
114	2	A-S	CL	4TXCB048BC3HCB	141353SY5G	4T CASED COIL	NO BOX,BACK SCRATCHED	\$102
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES SLIGHTLY PUSHED IN	\$77
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$212
2555	2	A-S	CU	2TTB3036A1000N	16033UBA5F	3T CONDENSER	LARGE DENT ON BOTTOM,COIL DAMAGE	\$377
2598	7	A-S	CU	4A6H6030H1000A	16065K5Y4F	2.5T HP CONDENSER	SLIGHT PANEL DENT,BASE CRACKED	\$651
2642	2	A-S	CU	4A6V0024A1000B	1625ZH141F	2T HEAT PUMP	SIDE PANEL DENTED	\$2,392
2081	6	A-S	CU	4A7A6030J1000A	16434HTM5F	2.5T CONDENSER	SIDE PANEL DENTED IN	\$893
139	9	A-S	CU	4A7A6030J1000A	16351KF55F	2.5T CONDENSER	DAMAGED ACCESS PANEL	\$970
2099	6	A-S	CU	4A7A6036J1000A	15471NE75F	3.0T 1S COND	TOP RIGHT CORNER SMOOSHED IN	\$608
2086	6	A-S	CU	4A7A6049J1000A	16155JJP2F	4T CONDENSER	VERY SLIGHT CRINKLE IN SIDE	\$1,248
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$1,293
2663	12	A-S	CU	4TTA3030A3000A	16151XE23F	2.5T 3PH CONDENSER	BRAND NEW OUT OF BOX	\$960
2624	2	A-S	CU	4TTA3030A3000A	16435N7P3F	2.5T 3PH CONDENSER	OUT OF BOX, OTHERWISE UNKOWN	\$882
2224	4	A-S	CU	TTA090A300G	15253560YA	7.5T CONDENSER	FINS BENT ON COIL	\$570
2055	12	A-S	CU	TWE120A300E	9213NB6BD	10T R22 CONV. AIR HANDLER	R22 UNIT STILL IN BOX	\$96
2351	7	A-S	FR	AUD1B080A9361B	16385RBA1G	80% GAS FURNACE	LEFT SIDE DENTRED,SUPPLY FLANGE BENT	\$410
2629	2	A-S	FR	AUD1C100A9481A	163553EC1G	80% UPFLW/HORZ-L GAS FURN	TOP REAR FLANGE BENT	\$456
2633	2	A-S	FR	AUD1C100A9481A	163553FT1G	80% UPFLW/HORZ-L GAS FURN	FRONT TOP DAMAGE & INDUCER	\$304
2634	2	A-S	FR	AUD2B060A9362A	16023SHC1G	80% UPFLW/HORZ-L 2S FURN	BOTTOM REAR-LARGE DENT	\$507
2683	2	A-S	FR	AUH1B040A9H21BA	171417SY2G	95% ECM 1S GAS FURNACE	DROPPED FROM LIFT, CORNER DENTED	\$288
2682	2	A-S	FR	AUH1B040A9H21BA	171311KA2G	95% ECM 1S GAS FURNACE	DROPPED FROM LIFT, CORNER DENTED	\$288
2274	10	A-S	FR	AUH1C100A9481CB	17135X392G	95% GAS FURNACE	SLIGHT DENT BACK BOTTOM	\$768
2467	2	A-S	FR	AUH2B060A936VA	14215LHK7G	90+ GAS FURNACE	OUT OF BOX	\$895
2175	8	A-S	FR	AUH2B080A9V3VB	15322RNP2G	97% GAS FURNACE	SCRATCHED,DENTED,MISSING INTAKE	\$810
2358	7	A-S	FR	AUHMB060ACV3VBC	16344NDP2G	97% GAS FURNACE	SLIGHT DAMAGE BACK OF CABINET	\$1,340
2405	11	A-S	FR	S9V2B060U3PSAA	16504MXG3G	96% 2 STG GAS FURNACE	SMALL DENTS	\$968
2647	2	A-S	FR	S9V2B080U3PSAA	16152L653G	96% GAS FURNACE	SLIGHT DENTS TO CABINET	\$902
2232	4	A-S	FR	S9V2C100U4PSAAB	17153HYX3G	96% 2STG GAS FURNACE	MINOR DENT LEFT SIDE	\$1,380
2679	2	A-S	RTU	YSC120F3RHA001S	154711333L	10T 208/3 GAS/ELEC ROOFTOP	SLIGHTLY DENTED ON CORNER	\$5,520

S. G. TORRICE COMPANY, INC. 06/09/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$384
2285	2	ASPEN	CL	CC48D44-175L-145	F15-00007822	4T CASSED COIL	UNKNOWN,RETURNED FOR SOME REASON	\$52
2427	2	ASPEN	CL	CE42B24-175L-015	F15-00029624	3.5T ASPEN COIL	SMALL DENT IN BACK	\$151
2552	2	ASPEN	CL	CE42B24-175L-015	K15-00010524	3.5T ASPEN COIL	PERFECT OUT OF BOX	\$140
2584	2	MIT	AH	MSZFE09NA		.75T WALL MOUNT HP	STILL IN BOX	\$164
2082	6	MIT	AH	MSZGL15NA	61E01843	1.25T WALL MOUNT HP AIR HANDLER	BOTTOM PLASTIC CRACKED	\$423
141	9	MIT	AH	MSZGL24NA-U1	5003240T	2.0T WALL MOUNT HEAT PUMP	CRACK IN TOP PANEL	\$405
2688	2	MIT	AH	MSZGL24NA-U1	6008131T	2T HEAT PUMP AIR HANDLER	CRACK IN CABINET	\$520
2272	10	MIT	AH	MVZA18NAA4	6XG01278	MULTI POSITION AIR HANDLER	TOP & BACK DENTED	\$990
2606	2	MIT	CU	MXZ3C24NA2-U1	52U01324B	3 ZONE 2.0T HP COND	MINOR COIL DAMAGE	\$936
2491	2	MIT	CU	MUZD30NA-1	7000101T	2.5T HEAT PUMP CONDENSER	BACK CENTER COIL DENTED	\$1,200
2492	2	MIT	CU	MUZFH06NA	63C00561	.5T HEAT PUMP CONDENSER	TINY PAINT CHIP ON FRONT CORNER	\$620
2354	2	MIT	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT,SIDE CABINET DAMAGE	\$662
2355	7	MIT	CU	MUZFH18NA2	6004404T	1.5T HYPERHEAT HP COND	NEEDS 1/2" VALVE,THREADS STRIPPED	\$738
2265	10	MIT	CU	MUZGE09NA2	5002801T	.75T HP COND	CORNER DENTED,PANEL WARPED	\$174
2681	2	MIT	CU	MUZGL18NA	6004961T	1.5T CONDENSER	LITTLE DENT TOP LEFT	\$931
2652	2	MIT	CU	MXZ2B20NA	6008594T	2 ZONE 1.5T HP COND	DENTED ON SIDE/SCRATCHED ON TOP	\$903
2173	8	MIT	CU	MXZ2C20NAHZ2-U1	69P03545	2 ZONE 1.5T HYPERHEAT CONDENSER	TOP & FRONT DENTED,BEEN INSTALLED	\$810
2079	6	MIT	CU	MXZ3C24NA2-U1	52U01322B	MIT 3 ZONE 2.0T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$1,410
2080	6	MIT	CU	MXZ3C30NA2-U1	54U02956C	MIT 3 ZONE 2.5T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$1,551
2298	2	MIT	CU	MXZ3C30NAHZ	5XP02214	MIT 3 ZONE 2.5T HYPERHEAT	LARGE DENT IN COIL	\$640
2266	10	MIT	CU	MXZ3C30NAHZ	4ZP01214	MIT 3 ZONE 2.5T HYPERHEAT	PANELS DENTED,POSSIBLE INTERNAL DAMAGE	\$1,160
2353	2	MIT	CU	MXZ3C30NAHZ2	63P00896	2.5T HYPERHEAT CONDENSER	FORKLIFT DAMAGE TO COIL	\$1,764
2169	8	MIT	CU	MXZ5C42NAHZ	6XU00278A	5 ZONE 3.5T HYPERHEAT	BIG DENT ON FRONT,COMPRESSOR LOOSE?	\$1,980
2273	10	MIT	CU	MXZ8C48NAHZ-U1	6XU00126A	8 ZONE 4.0T HYPERHEAT CONDENSER	COIL FINS & COIL GUARD BENT	\$2,820
2085	6	MIT	CU	MXZ8C48NAHZ-U1	63U00816B	8 ZONE 4T HYPERHEAT CONDENSER	MULTIPLE DENTS ON CABINET	\$3,000
119	2	MIT	CU	SUZKA12NA.TH	51P00287	1T HEAT PUMP CONDENSER	SMALL DENTS ALL AROUND	\$124
2335	2	REZ	HTR	UDAP150	BOD796EN69889X	UNIT HEATER	SMALL DENT,2 DEFLECTORS MISSING	\$264
2666	12	TR	AH	TAM4A0A30S21ED	17212PSD1V	TRANE 2.5T AIR HANDLER	LEFT SIDE CABINET DENTED	\$725
2665	12	TR	AH	TAM4A0A36S31ED	172132KE1V	TRANE 3T AIR HANDLER	LEFT SIDE SCRATCHED AND DENTED	\$800
2174	8	TR	CL	4TXCB003DS3HCA	16424RXE5G	TRANE 1.5-2.5T HI-EFF CSD COIL	NO PRESSURE,POSSIBLE LEAK	\$135
2660	12	TR	CU	4TTR3030H1000N	16512R89AF	2.5T CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$624
2659	12	TR	CU	4TTR3030H1000N	16512S3PAF	2.5T CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$624
2662	12	TR	CU	4TTR3030H1000N	17172PDGAF	2.5T CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$624
2664	12	TR	CU	4TTV0036B1000B	17223RLX1F	3T VS CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$2,450
2230	4	TR	FR	TDHMB060BCV3VB	16511N257G	95% MODULATING FURNACE	PREVIOUSLY INSTALLED	\$1,344

S. G. TORRICE COMPANY, INC. 06/09/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$384
2657	12	TR	FR	TUD1B080A9361	16475UW31G	80% GAS FURNACE	LEFT SIDE CABINET PUSHED IN	\$418
2656	12	TR	FR	TUH1B060A9H31B	17082RBC2G	TRANE 95% GAS FURNACE	TOP LEFT CORNER CRUSHED	\$630
2275	10	TR	FR	TUH1B080A9421CB	16494JUM2G	95% GAS FURNACE	OUT OF BOX, MINOR SCRATCHES	\$828