

S. G. TORRICE COMPANY, INC. 07/26/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$348
2464	2	A-S	AH	GAF2A0A36S31EEA	17205LL01V	3T AIR HANDLER	SMALL DENTS BACK OF UNIT	\$624
950	7	A-S	AH	GAM2A0B42S31SEA	1514137ABV	3.5T CONV AIR HANDLER	LEAK IN COIL,NEEDS NEW COIL	\$32
2361	7	A-S	AH	TAM7A0A24H21EA	16183N0NBV	3T AIR HANDLER	BOTTOM CORNER DAMAGED	\$893
2463	2	A-S	AH	TAM7A0A24V21DAA	172250TU1V	2T AIR HANDLER	RIGHT SIDE BACK OF UNIT DENTED	\$864
2549	2	A-S	AH	TAM7A0B30H21EA	16273SNTAV	2.5T VS AIR HANDLER	SCRATCHED & DENTED ALL OVER	\$950
2364	7	A-S	AH	TAM7A0C36H31EAA	17105N6P1V	3.0T CONV VS AIR HANDLER	BACK CORNER SLIGHT DAMAGE	\$1,000
2564	2	A-S	AH	TAM8C0C36V1EAA	16113TE4AY	3T AIR HANDLER	REAR OF CABINET DENTED	\$486
142	9	A-S	AH	TAM9A0A24V21DA	17171N771V	2T VS AIR HANDLER	TOP RIGHT SIDE PUSHED IN	\$893
2495	2	A-S	AH	TAM9A0C42V41DAA	17174L5H1V	3.5T AIR HANDLER	TOP BACK OF UNIT CRUSHED	\$912
2365	7	A-S	AH	TAM9A0C48V41DA	171814691V	4.0T VS CONV AIR HANDLER	BACK LEFT CORNER DAMAGED	\$950
2692	2	A-S	AH	TAM9A0C48V41DAA	1717224E1V	4T AIR HANDLER	TOP BACK RIGHT CORNER SMASHED	\$816
2694	2	A-S	AH	TEM4A0B24S21SA	172421RN3V	2T AIR HANDLER	BACK RIGHT CORNER DENTED	\$432
2084	6	A-S	AH	TEM4A0B30S31SA	17225YNK3V	2.5T CONV AIR HANDLER	NOISY BLOWER WHEEL	\$400
2486	2	A-S	AH	TEM4A0B30S31SAA	17175A9S3V	2.5T AIR HANDLER	BACK RIGHT CORNER CRUSHED	\$384
2695	2	A-S	AH	TEM4A0B30S31SAA	17182H1N3V	2.5T AIR HANDLER	LARGE DENT TOP REAR	\$450
2697	2	A-S	AH	TEM4A0B30S31SAA	17175APX3V	2.5T AIR HANDLER	TOP BACK LEFT CORNER CRUSHED	\$450
2482	2	A-S	AH	TEM4A0C36S41SAA	171824423V	3T AIR HANDLER	DENTED TOP & BACK,BLOWER HSG DAMAGED	\$450
2485	2	A-S	AH	TEM4A0C36S41SAA	17253YPT3V	3T AIR HANDLER	BACK TOP OF UNIT CRUSHED	\$450
2496	2	A-S	AH	TEM4A0C42S41SAA	17204JP02V	3.5T AIR HANDLER	BLOWER HOUSING DAMGED, DENTED	\$517
143	9	A-S	AH	TEM4A0C42S41SAA	172240A43V	3.5T AIR HANDLER	REAR CABINET DENTED TOP & BOTTOM	\$600
2286	2	A-S	CL	4TXCA024BC3HCB	15472K1DBG	2T CASED COIL	TOP REAR DENTED	\$72
2586	7	A-S	CL	4TXCB006DS3HCAA	16354JRR5G	3.5-4.0T HI-EFF CSD COIL	MINOR DAMAGE TO BACK CORNER	\$205
946	7	A-S	CL	4TXCB048BC3HCB	152642X2BG	4T CASED COIL	DENTED TOP RIGHT CORNER	\$45
114	2	A-S	CL	4TXCB048BC3HCB	141353SY5G	4T CASED COIL	NO BOX,BACK SCRATCHED	\$82
2371	7	A-S	CL	4TXCC009DS3HCA	16435YLHCG	5.0T HI-EFF CSD COIL	FRONT CABINET DENTED	\$406
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES SLIGHTLY PUSHED IN	\$56
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$190
2555	2	A-S	CU	2TTB3036A1000N	16033UBA5F	3T CONDENSER	LARGE DENT ON BOTTOM,COIL DAMAGE	\$338
2642	2	A-S	CU	4A6V0024A1000B	1625ZH141F	2T HEAT PUMP	SIDE PANEL DENTED	\$2,236
2700	2	A-S	CU	4A7A3024H1000N	173021S7AF	2T CONDENSER	SIDE PANEL DAMAGED	\$700
2375	7	A-S	CU	4A7A3024H1000N	17242XXPAF	2T CONDENSER	MULTIPLE DENTS ON PANELS	\$650
2691	2	A-S	CU	4A7A3036H1000N	1720341N3F	3T CONDENSER	BASE PAN CRACKED	\$714
2081	6	A-S	CU	4A7A6030J1000A	16434HTM5F	2.5T CONDENSER	SIDE PANEL DENTED IN	\$836
2696	2	A-S	CU	4A7A6030J1000A	17264HXR5F	2.5T CONDENSER	SIDE PANEL SMALL DENT	\$980
2099	6	A-S	CU	4A7A6036J1000A	15471NE75F	3.0T 1S COND	TOP RIGHT CORNER SMOOSHED IN	\$560

S. G. TORRICE COMPANY, INC. 07/26/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$348
2086	6	A-S	CU	4A7A6049J1000A	16155JJP2F	4T CONDENSER	VERY SLIGHT CRINKLE IN SIDE	\$1,170
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$1,210
2663	12	A-S	CU	4TTA3030A3000A	16151XE23F	2.5T 3PH CONDENSER	BRAND NEW OUT OF BOX	\$902
2624	2	A-S	CU	4TTA3030A3000A	16435N7P3F	2.5T 3PH CONDENSER	OUT OF BOX, OTHERWISE UNKOWN	\$828
2224	4	A-S	CU	TTA090A300G	15253560YA	7.5T CONDENSER	FINS BENT ON COIL	\$456
2055	12	A-S	CU	TWE120A300E	9213NB6BD	10T R22 CONV. AIR HANDLER	R22 UNIT STILL IN BOX	\$96
2351	7	A-S	FR	AUD1B080A9361B	16385RBA1G	80% GAS FURNACE	LEFT SIDE DENTRED,SUPPLY FLANGE BENT	\$360
2373	7	A-S	FR	AUD1B100A9361AB	171636P51G	80% GAS FURNACE	INSTALLED, LEFT SIDE RETURN CUT OUT	\$500
2629	2	A-S	FR	AUD1C100A9481A	163553EC1G	80% UPFLW/HORZ-L GAS FURN	TOP REAR FLANGE BENT	\$420
2633	2	A-S	FR	AUD1C100A9481A	163553FT1G	80% UPFLW/HORZ-L GAS FURN	FRONT TOP DAMAGE & INDUCER	\$280
2634	2	A-S	FR	AUD2B060A9362A	16023SHC1G	80% UPFLW/HORZ-L 2S FURN	BOTTOM REAR-LARGE DENT	\$468
2683	2	A-S	FR	AUH1B040A9H21BA	171417SY2G	95% ECM 1S GAS FURNACE	DROPPED FROM LIFT, CORNER DENTED	\$270
2682	2	A-S	FR	AUH1B040A9H21BA	171311KA2G	95% ECM 1S GAS FURNACE	DROPPED FROM LIFT, CORNER DENTED	\$270
2370	7	A-S	FR	AUH1B080A9H31CA	16443G072G	95% GAS FURNACE	BOTTOM RIGHT CORNER SLIGHT DAMAGE	\$850
2698	2	A-S	FR	AUH1C100A9481A	17242XFD2G	95% GAS FURNACE	LARGE DENT BOTTOM REAR	\$875
2467	2	A-S	FR	AUH2B060A936VA	14215LHK7G	90+ GAS FURNACE	OUT OF BOX	\$840
2175	8	A-S	FR	AUH2B080A9V3VB	15322RNP2G	97% GAS FURNACE	SCRATCHED,DENTED,MISSING INTAKE	\$756
2358	7	A-S	FR	AUHMB060ACV3VBC	16344NDP2G	97% GAS FURNACE	SLIGHT DAMAGE BACK OF CABINET	\$1,254
2647	2	A-S	FR	S9V2B080U3PSAA	16152L653G	96% GAS FURNACE	SLIGHT DENTS TO CABINET	\$792
2490	2	A-S	FR	S9V2C100U5PSAA	17231P1Y3G	96% 2STG GAS FURNACE	TOP RIGHT CORNER CRUSHED	\$1,222
2679	2	A-S	RTU	YSC120F3RHA001S	154711333L	10T 208/3 GAS/ELEC ROOFTOP	SLIGHTLY DENTED ON CORNER	\$5,160
2285	2	ASPEN	CL	CC48D44-175L-145	F15-00007822	4T CASED COIL	UNKNOWN,RETURNED FOR SOME REASON	\$40
2427	2	ASPEN	CL	CE42B24-175L-015	F15-00029624	3.5T ASPEN COIL	SMALL DENT IN BACK	\$135
2552	2	ASPEN	CL	CE42B24-175L-015	K15-00010524	3.5T ASPEN COIL	PERFECT OUT OF BOX	\$125
2584	2	MIT	AH	MSZFE09NA		.75T WALL MOUNT HP	STILL IN BOX	\$144
2367	7	MIT	AH	MSZFH06NA	7000611T	.50T WALL MOUNT HP AH	FRONT SCUFFED,MISSING REMOTE	\$275
2368	7	MIT	AH	MSZFH09NA	5007022T	.75T WALL MOUNT HP	FRONT COVER & FAN BLADES BROKEN	\$200
2369	7	MIT	AH	MSZFH09NA	6011997T	.75T WALL MOUNT HP	NEEDS RIGHT CORNER ELEC. PANEL	\$275
2693	2	MIT	AH	MSZFH18NA2	6011182T	1.5T WALL MOUNT HP AIR HANDLER	WAS INSTALLED	\$500
2082	6	MIT	AH	MSZGL15NA	61E01843	1.25T WALL MOUNT HP AIR HANDLER	BOTTOM PLASTIC CRACKED	\$396
2468	2	MIT	AH	MSZGL15NA-U1	74E22485	1.25T WALL MOUNT HP	BOTTOM CRACKED	\$400
2548	2	MIT	AH	MSZGL15NA-U1	75E23645	1.25T WALL MOUNT HEAT PUMP	FRONT PANEL CRACKED,BACK MT CRUSHED	\$400
2688	2	MIT	AH	MSZGL24NA-U1	6008131T	2T HEAT PUMP AIR HANDLER	CRACK IN CABINET	\$489
2272	10	MIT	AH	MVZA18NAA4	6XG01278	MULTI POSITION AIR HANDLER	TOP & BACK DENTED	\$924
2366	7	MIT	CU	MSZD30NA	6001562T	2.5T HP CONDENSER	SUCTION FLARE LEAKS, MANY SCRATCHES	\$950

S. G. TORRICE COMPANY, INC. 07/26/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2406	2	A-S	AH	GAF2A0A24S21EE	16154K2EBV	2T AIR HANDLER	BACK BOTTOM CORNER CRUSHED	\$348
2491	2	MITS	CU	MUZD30NA-1	7000101T	2.5T HEAT PUMP CONDENSER	BACK CENTER COIL DENTED	\$1,128
2492	2	MITS	CU	MUZFH06NA	63C00561	.5T HEAT PUMP CONDENSER	TINY PAINT CHIP ON FRONT CORNER	\$583
2354	2	MITS	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT, SIDE CABINET DAMAGE	\$621