

S. G. TORRICE COMPANY, INC. 10/04/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED'BACK LEFT CORNER DENTED	\$800
2365	7	A-S	AH	TAM9A0C48V41DA	171814691V	4.0T VS CONV AIR HANDLER	BACK LEFT CORNER DAMAGED	\$893
2694	2	A-S	AH	TEM4A0B24S21SA	172421RN3V	2T AIR HANDLER	BACK RIGHT CORNER DENTED	\$387
2695	2	A-S	AH	TEM4A0B30S31SAA	17182H1N3V	2.5T AIR HANDLER	LARGE DENT TOP REAR	\$423
2697	2	A-S	AH	TEM4A0B30S31SAA	17175APX3V	2.5T AIR HANDLER	TOP BACK LEFT CORNER CRUSHED	\$423
2482	11	A-S	AH	TEM4A0C36S41SAA	171824423V	3T AIR HANDLER	DENTED TOP & BACK,BLOWER HSG DAMAGED	\$423
2485	11	A-S	AH	TEM4A0C36S41SAA	17253YPT3V	3T AIR HANDLER	BACK TOP OF UNIT CRUSHED	\$423
2496	2	A-S	AH	TEM4A0C42S41SAA	17204JP02V	3.5T AIR HANDLER	BLOWER HOUSING DAMGED, DENTED	\$473
143	9	A-S	AH	TEM4A0C42S41SAA	172240A43V	3.5T AIR HANDLER	REAR CABINET DENTED TOP & BOTTOM	\$564
2384	7	A-S	AH	TEM4A0C42S41SAA	17295P293V	3.5T VS AIR HANDLER	BLOWER WHEEL OUT OF BALANCE/DENTED	\$300
	12	A-S	CL	4MXCA001AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 25 TOTAL	\$196
	12	A-S	CL	4MXCB002AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 127 TOTAL	\$221
	12	A-S	CL	4MXCB004AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 58 TOTAL	\$245
	12	A-S	CL	4MXCB006AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 23 TOTAL	\$255
	12	A-S	CL	4MXCC005AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 22 TOTAL	\$245
	12	A-S	CL	4MXCC007AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 27 TOTAL	\$270
	12	A-S	CL	4MXCC009AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 13 TOTAL	\$294
	12	A-S	CL	4MXCD008AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 12 TOTAL	\$343
	12	A-S	CL	4MXCD010AC6HCA		3.5T-5T CONV. CASED COIL	PERFECT CONDITION 26 TOTAL	\$343
2586	7	A-S	CL	4TXCB006DS3HCAA	16354JRR5G	3.5-4.0T HI-EFF CSD COIL	MINOR DAMAGE TO BACK CORNER	\$143
946	7	A-S	CL	4TXCB048BC3HCB	152642X2BG	4T CASED COIL	DENTED TOP RIGHT CORNER	\$34
114	2	A-S	CL	4TXCB048BC3HCB	141353SY5G	4T CASED COIL	NO BOX,BACK SCRATCHED	\$61
2371	7	A-S	CL	4TXCC009DS3HCA	16435YLHCG	5.0T HI-EFF CSD COIL	FRONT CABINET DENTED	\$382
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES PUSHED IN, NOT TOO BAD	\$196
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$168
2642	2	A-S	CU	4A6V0024A1000B	1625ZH141F	2T HEAT PUMP	SIDE PANEL DENTED	\$2,080
2700	2	A-S	CU	4A7A3024H1000N	173021S7AF	2T CONDENSER	SIDE PANEL DAMAGED	\$658
2375	7	A-S	CU	4A7A3024H1000N	17242XXPAF	2T CONDENSER	MULTIPLE DENTS ON PANELS	\$611
2093	6	A-S	CU	4A7A3024H1000N	17251648AF	2T CONDENSER	SMALL DENT BOTTOM BACK PANEL	\$637
824	6	A-S	CU	4A7A3024H1000N		2T CONDENSER	PLASTIC BASE CHIPPED	\$707
595	6	A-S	CU	4A7A3030H1000N		2.5T CONDENSER	SMALL SCRATCH/SMALL DENT TO REAR	\$706
818	6	A-S	CU	4A7A3036H1000N		3T CONDENSER	BACK BOTTOM PANEL DENTED	\$838
2756	2	A-S	CU	4A7A3036H1000N	173436MD3F	3T CONDENSER	BASE PANEL CHIPPED	\$838
2092	6	A-S	CU	4A7A6042J1000N	17242JEE5F	3.5T 1S CONDENSER	SMALL DENT BOTTOM RIGHT SIDE PANEL	\$1,127
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$1,128
2483	11	A-S	CU	4A7A7024A1000B	17304JW02F	16/17 SEER 2.0T 2S CONDENSER	TOP LEFT SIDE BADLY DENTED	\$1,127

S. G. TORRICE COMPANY, INC. 10/04/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED'BACK LEFT CORNER DENTED	\$800
2624	2	A-S	CU	4TTA3030A3000A	16435N7P3F	2.5T 3PH CONDENSER	OUT OF BOX, OTHERWISE UNKOWN	\$774
2055	12	A-S	CU	TWE120A300E	9213NB6BD	10T R22 CONV. AIR HANDLER	R22 UNIT STILL IN BOX	\$96
2351	7	A-S	FR	AUD1B080A9361B	16385RBA1G	80% GAS FURNACE	LEFT SIDE DENTRED,SUPPLY FLANGE BENT	\$330
2373	7	A-S	FR	AUD1B100A9361AB	171636P51G	80% GAS FURNACE	INSTALLED, LEFT SIDE RETURN CUT OUT	\$470
2088	6	A-S	FR	S9V2B080U3PSAA	17141U9Y3G	96% GAS FURNACE	DOOR DENTED, TOP LEFT CORNER DENTED	\$1,163
2234	4	A-S	FR	S9V2D120U5PSAA	17335PYY3G	96% 2STG GAS FURNACE	SMALL DENTS TO TOP AND REAR	\$1,274
	2	A-S	RTU	WSC060H3RJA003Q		5T PACKAGED HEAT PUMP	DEALER RETURN 5 TOTAL	\$3,648
2679	2	A-S	RTU	YSC120F3RHA001S	154711333L	10T 208/3 GAS/ELEC ROOFTOP	SLIGHTLY DENTED ON CORNER	\$4,800
2285	2	ASPEN	CL	CC48D44-175L-145	F15-00007822	4T CASED COIL	UNKNOWN, RETURNED FOR SOME REASON	\$32
2367	7	MIT	AH	MSZFH06NA	7000611T	.50T WALL MOUNT HP AH	FRONT SCUFFED, MISSING REMOTE	\$259
2368	7	MIT	AH	MSZFH09NA	5007022T	.75T WALL MOUNT HP	FRONT COVER & FAN BLADES BROKEN	\$188
2369	7	MIT	AH	MSZFH09NA	6011997T	.75T WALL MOUNT HP	NEEDS RIGHT CORNER ELEC. PANEL	\$259
2279	10	MIT	AH	MSZFH15NA	7003442T	1.25T HEAT PUMP AIR HANDLER	BOTTOM PANEL CRACKED	\$245
2468	11	MIT	AH	MSZGL15NA-U1	74E22485	1.25T WALL MOUNT HP	BOTTOM CRACKED	\$376
2548	11	MIT	AH	MSZGL15NA-U1	75E23645	1.25T WALL MOUNT HEAT PUMP	FRONT PANEL CRACKED, BACK MT CRUSHED	\$376
2272	10	MIT	AH	MVZA18NAA4	6XG01278	MULTI POSITION AIR HANDLER	TOP & BACK DENTED	\$858
2366	7	MIT	CU	MSZD30NA	6001562T	2.5T HP CONDENSER	SUCTION FLARE LEAKS, MANY SCRATCHES	\$893
2354	2	MIT	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT, SIDE CABINET DAMAGE	\$581
2090	2	MIT	CU	MUZFH09NA-1	74C03266	.75T HEAT PUMP CONDENSER	SIDE DENTED	\$490
2091	2	MIT	CU	MUZFH12NA	76C08310	1T HEAT PUMP CONDENSER	SIDE DENTED	\$637
2355	7	MIT	CU	MUZFH18NA2	6004404T	1.5T HYPERHEAT HP COND	NEEDS 1/2" VALVE, THREADS STRIPPED	\$594
2265	10	MIT	CU	MUZGE09NA2	5002801T	.75T HP COND	CORNER DENTED, PANEL WARPED	\$104
2681	2	MIT	CU	MUZGL18NA	6004961T	1.5T CONDENSER	LITTLE DENT TOP LEFT	\$817
2652	2	MIT	CU	MXZ2B20NA	6008594T	2 ZONE 1.5T HP COND	DENTED ON SIDE/SCRATCHED ON TOP	\$693
2173	8	MIT	CU	MXZ2C20NAHZ2-U1	69P03545	2 ZONE 1.5T HYPERHEAT CONDENSE	TOP & FRONT DENTED, BEEN INSTALLED	\$702
2079	6	MIT	CU	MXZ3C24NA2-U1	52U01322B	MIT 3 ZONE 2.0T HP CONDENSER	OUT OF BOX, SLIGHTLY SCUFFED	\$1,230
2690	2	MIT	CU	MXZ3C24NA-U1	6YU08458A	3 ZONE 2.0T HP CONDENSER	HAS BEEN INSTALLED	\$1,204
2080	6	MIT	CU	MXZ3C30NA2-U1	54U02956C	MIT 3 ZONE 2.5T HP CONDENSER	OUT OF BOX, SLIGHTLY SCUFFED	\$1,353
2266	10	MIT	CU	MXZ3C30NAHZ	4ZP01214	MIT 3 ZONE 2.5T HYPERHEAT	PANELS DENTED, POSSIBLE INTERNAL DAMAG	\$920
2353	2	MIT	CU	MXZ3C30NAHZ2	63P00896	2.5T HYPERHEAT CONDENSER	FORKLIFT DAMAGE TO COIL	\$1,548
2277	10	MIT	CU	MXZ3C30NAHZ-2	67P038	3 ZONE 2.5T HYPERHEAT CONDENSE	FRAME BENT, FINS BENT, SIDE DENTED	\$1,410
2753	2	MIT	CU	MXZ4C36NH2-U1	53U01937B	4 ZONE 3T HEAT PUMP CONDENSER	MINOR SCRATCHES ON TOP	\$1,666
2273	10	MIT	CU	MXZ8C48NAHZ-U1	6XU00126A	8 ZONE 4.0T HYPERHEAT CONDENSE	COIL FINS & COIL GUARD BENT	\$2,460
2462	11	MIT	CU	PUZA36NKA7	77V01824D	3T HEAT PUMP CONDENSER	COIL FINS DENTED	\$1,568
2699	2	MIT	CU	SUZKA12NA.TH	68P01617	MIT. 1T HP CONDENSER	TOP CORNER DENTED, RIGHT PANEL BENT	\$637

S. G. TORRICE COMPANY, INC. 10/04/2017

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED'BACK LEFT CORNER DENTED	\$800
2547	11	MIT	CU	SUZKA15NA	6XP01392	MIT 1.25T HP CONDENSER	SIDE CRUSHED IN	\$624
2667	12	REZ	HTR	UDAP250	BPD3062024466	REZNOR UNIT HEATER	RIGHT FRONT CORNER CRUSHED BIGLY	\$516
2236	4	RNW	ERV	EV300	G177088R	RENEWAIRE ERV	DENTED	\$825