

Distressed/Obsolete Equipment List



1/11/2018

First Come, First Served - NO HELD ITEMS
Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$494
2543	11	A-S	AH	GAF2A0A24S21EE	17175J351V	2T AIR HANDLER	BACK PANEL DAMAGED	\$517
2545	11	A-S	AH	GAF2A0A24S21EEA	17175J211U	2T AIR HANDLER	CORNER DENTED IN	\$494
2461	11	A-S	AH	GAF2A0A30S21E	1721MM41V	2.5T AIR HANDLER	TOP CORNER DAMAGED	\$495
2464	11	A-S	AH	GAF2A0A36S31EEA	17205LL01V	3T AIR HANDLER	SMALL DENTS BACK OF UNIT	\$507
950	7	A-S	AH	GAM2A0B42S31SEA	1514137ABV	3.5T CONV AIR HANDLER	LEAK IN COIL,NEEDS NEW COIL	\$20
2850	2	A-S	AH	M4AH3036B1000A	170131396M	3T AIR HANDLER	SCRAP AND A DING IN THE FRONT	\$384
2853	2	A-S	AH	M4AH3048B1000A	164260056M	4T AIR HANDLER	SMALL DENT FRONT CORNER COIL STUB BENT	\$432
2361	7	A-S	AH	TAM7A0A24H21EA	16183N0NBV	3T AIR HANDLER	BOTTOM CORNER DAMAGED	\$741
2463	11	A-S	AH	TAM7A0A24V21DAA	172250TU1V	2T AIR HANDLER	RIGHT SIDE BACK OF UNIT DENTED	\$702
142	9	A-S	AH	TAM9A0A24V21DA	17171N771V	2T VS AIR HANDLER	TOP RIGHT SIDE PUSHED IN	\$741
2382	7	A-S	AH	TAM9A0A24V21DA	17191XDA1V	2T VS AIR HANDLER	BLOWER HOUSING SAGS IN HORZ. POSITION	\$552
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED/BACK LEFT CORNER DENTED	\$736
2799	7	A-S	AH	TAM9A0A24V21DA	17395KWB1V	2T CONV. AIR HANDLER	DOOR DAMAGED/SLIGHT DENT TOP LEFT	\$912
2862	2	A-S	AH	TAM9A0A24V21DA	17201NLC1V	2T AIR HANDLER	PLASTIC PIECES BROKEN OFF INSIDE?	\$970
2694	2	A-S	AH	TEM4A0B24S21SA	172421RN3V	2T AIR HANDLER	BACK RIGHT CORNER DENTED	\$351
2542	11	A-S	AH	TEM4A0B24S21SA	172636703U	2T CONV. AIR HANDLER	NO GAS IN COIL,DENTED TOP & SIDE	\$240
2695	2	A-S	AH	TEM4A0B30S31SAA	17182H1N3V	2.5T AIR HANDLER	LARGE DENT TOP REAR	\$387
2697	2	A-S	AH	TEM4A0B30S31SAA	17175APX3V	2.5T AIR HANDLER	TOP BACK LEFT CORNER CRUSHED	\$387
2482	11	A-S	AH	TEM4A0C36S41SAA	171824423V	3T AIR HANDLER	DENTED TOP & BACK,BLOWER HSG DAMAGED	\$387
2485	11	A-S	AH	TEM4A0C36S41SAA	17253YPT3V	3T AIR HANDLER	BACK TOP OF UNIT CRUSHED	\$387
2496	2	A-S	AH	TEM4A0C42S41SAA	17204JP02V	3.5T AIR HANDLER	BLOWER HOUSING DAMGED, DENTED	\$429
143	9	A-S	AH	TEM4A0C42S41SAA	172240A43V	3.5T AIR HANDLER	REAR CABINET DENTED TOP & BOTTOM	\$516
2384	7	A-S	AH	TEM4A0C42S41SAA	17295P293V	3.5T VS AIR HANDLER	BLOWER WHEEL OUT OF BALANCE/DENTED	\$552
2536	11	A-S	AH	TEM4A0C48S41SA	17312D313V	4T AIR HANDLER	DENTED BACK AND LEFT SIDES BOTTOM	\$528
2541	11	A-S	AH	TEM4A0C48S41SAA	17385YC3V	4T AIR HANDLER	TOP RIGHT CORNER DENTED	\$637
12	A-S	CL		4MXCA001AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 20 TOTAL	\$180
12	A-S	CL		4MXCB002AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 102 TOTAL	\$203
12	A-S	CL		4MXCB004AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 50 TOTAL	\$225
12	A-S	CL		4MXCB006AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 22 TOTAL	\$234
12	A-S	CL		4MXCC005AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 21 TOTAL	\$225
12	A-S	CL		4MXCC007AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 26 TOTAL	\$248
12	A-S	CL		4MXCC009AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 11 TOTAL	\$270
12	A-S	CL		4MXCD008AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 11 TOTAL	\$315
12	A-S	CL		4MXCD010AC6HCA		3.5T-5T CONV. CASED COIL	PERFECT CONDITION 28 TOTAL	\$315
188	8	A-S	CL	4TXCB004DS3HCA	17345LCE5G	3T CASED COIL	SMALL DENT BACK SIDE	\$259
2566	2	A-S	CL	4TXCB004DS3HCAA	162635NGCG	3T CASED COIL	RIGHT CORNER DENTED	\$240
2586	7	A-S	CL	4TXCB006DS3HCAA	16354JRR5G	3.5-4.0T HI-EFF CSD COIL	MINOR DAMAGE TO BACK CORNER	\$118
946	7	A-S	CL	4TXCB048BC3HCB	152642X2BG	4T CASED COIL	DENTED TOP RIGHT CORNER	\$28
2371	7	A-S	CL	4TXCC009DS3HCA	16435YLHCG	5.0T HI-EFF CSD COIL	FRONT CABINET DENTED	\$349
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES PUSHED IN, NOT TOO BAD	\$180
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$139
2642	2	A-S	CU	4A6V0024A1000B	1625ZH141F	2T HEAT PUMP	SIDE PANEL DENTED	\$1,820
2238	4	A-S	CU	4A6V8036A1000B	17101J1M1F	3T VS HEAT PUMP	2 PANELS SMALL DENTS/BASE CRACKED	\$1,872
2758	2	A-S	CU	4A7A3018H1000N	17164MUF4F	1.5T CONDENSER	FORKLIFT DAMAGE TO BASE	\$517
2700	2	A-S	CU	4A7A3024H1000N	173021S7AF	2T CONDENSER	SIDE PANEL DAMAGED	\$602
2375	7	A-S	CU	4A7A3024H1000N	17242XXPAF	2T CONDENSER	MULTIPLE DENTS ON PANELS	\$559
2093	6	A-S	CU	4A7A3024H1000N	17251648AF	2T CONDENSER	SMALL DENT BOTTOM BACK PANEL	\$585
824	6	A-S	CU	4A7A3024H1000N		2T CONDENSER	PLASTIC BASE CHIPPED	\$650
2759	2	A-S	CU	4A7A3024H1000N	17054TY8AF	2T CONDENSER	BOTTOM CORNER DENTED	\$552
2281	10	A-S	CU	4A7A3030H1000N	17063TPRAF	2.5T CONDENSER	DENTED LEFT SIDE COIL PUSHED IN	\$541
2756	2	A-S	CU	4A7A3036H1000N	173436MD3F	3T CONDENSER	BASE PANEL CHIPPED	\$771
2857	2	A-S	CU	4A7A3042E1000N	17321JU7AF	3.5T CONDENSER	SIDE PANEL VERY SLIGHTLY PUSHED IN	\$890
2854	2	A-S	CU	4A7A4018L1000A	17283YKWAF	1.5T CONDENSER	CRACKED BASE PAN	\$600
2797	7	A-S	CU	4A7A6024J1000A	17223L613F	2T CONDENSER	BASE PAN CHIPPED	\$816
2386	7	A-S	CU	4A7A6030J1000A	17255MFJ5F	2.5T CONDENSER	TOP COVER,FRONT PANEL DAMAGED	\$846
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$1,018
2483	11	A-S	CU	4A7A7024A1000B	17304JW02F	16/17 SEER 2.0T 2S CONDENSER	TOP LEFT SIDE BADLY DENTED	\$1,035
2711	12	A-S	CU	4A7C3048D3000D	17323NWXG3F	4.0T 208/3 CONDENSER	BASE PAN CHIPPED	\$1,222
2802	7	A-S	CU	4A7V8024A1000A	17151M5E1F	2T 18SEER CONDENSER	CHIP IN BASE PAN,LEFT PANEL DENTED	\$1,490
2851	2	A-S	CU	4MAC3018B1000H	164020156M	1.5T CONDENSER	LARGE DENT ON CORNER POST	\$432
2860	2	A-S	CU	M4AC3018B1000A	172060437M	AMERISTAR 1.5T CONDENSER	SIDE PANEL DENTED	\$500
2852	2	A-S	CU	M4AC3018B1000N	171520168M	1.5T CONDENSER	SMALL DENT TO CORNER POST	\$480
2055	12	A-S	CU	TWE120A300E	9213NB6BD	10T R22 CONV. AIR HANDLER	R22 UNIT STILL IN BOX	\$96
2537	11	A-S	FR	AUD1B080A9361B	17444PGM1G	80% GAS FURNACE	FRONT TOP DAMAGED	\$466
2538	11	A-S	FR	AUD2B080A9362A	164040W11G	80% 2STG GAS FURNACE	BACK RIGHT CORNER DENTED	\$730

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2241	4	A-S	FR	AUH1B060A9361C	17122W1A2G	95% GAS FURNACE	TOP SMASHED,BOTH DOORS SMASHED	\$550
2800	7	A-S	FR	AUH2B060A9V3VB	174028R12G	97% GAS FURNACE	BLOWER DOOR PUNCTURED	\$1,056
2856	2	A-S	FR	S9V2B060U3PSBA	1748178N3G	96% 2STG GAS FURNACE	SMALL DING TOP CORNER	\$1,137
2	A-S	RTU	WSC060H3RJA003Q			5T PACKAGED HEAT PUMP	DEALER RETURN 4 TOTAL	\$3,344
2	A-S	RTU	YCZ060E4RHA26L8	15181567L		5T ROOFTOP		\$480
2	A-S	RTU	YHC102F3RHA25DU	173213648L		8.5T HI-EFF ROOFTOP		\$5,760
2	A-S	RTU	YHC120F4RHA001S	154711957L		10T HI-EFF ROOFTOP		\$6,720
2	A-S	RTU	YSC090F4RHA001S	172510628L		10T ROOFTOP		\$384
2	A-S	RTU	YSC090F4RHA001S	153710669L		7.5T ROOFTOP		\$3,840
2	A-S	RTU	YSC090F4RHA001S	150811997L		7.5T ROOFTOP		\$3,840
2285	2	ASPEN	CL	CC48D44-175L-145	F15-00007822	4T CASED COIL	UNKNOWN,RETURNED FOR SOME REASON	\$20
2367	7	MIT	AH	MSZFH06NA	7000611T	.50T WALL MOUNT HP AH	FRONT SCUFFED,MISSING REMOTE	\$237
2368	7	MIT	AH	MSZFH09NA	5007022T	.75T WALL MOUNT HP	FRONT COVER & FAN BLADES BROKEN	\$172
2369	7	MIT	AH	MSZFH09NA	6011997T	.75T WALL MOUNT HP	NEEDS RIGHT CORNER ELEC. PANEL	\$237
2279	10	MIT	AH	MSZFH15NA	7003442T	1.25T HEAT PUMP AIR HANDLER	BOTTOM PANEL CRACKED	\$225
192	8	MIT	AH	MSZFH18NA2	7008700T	1.5T HEAT PUMP AIR HANDLER	CRACK IN COVER,RIGHT SIDE	\$423
2468	11	MIT	AH	MSZGL15NA-U1	74E22485	1.25T WALL MOUNT HP	BOTTOM CRACKED	\$344
2548	11	MIT	AH	MSZGL15NA-U1	75E23645	1.25T WALL MOUNT HEAT PUMP	FRONT PANEL CRACKED,BACK MT CRUSHED	\$344
191	8	MIT	AH	MSZGL18NA-U1	3012801T	1.5T HEAT PUMP AIR HANDLER	COVER CRACKED BOTTOM RIGHT CORNER	\$376
2858	2	MIT	AH	MSZGL18NA-U1	7007381T	1.5T HP AIR HANDLER	CRACKED HOUSING	\$441
2272	10	MIT	AH	MVZA18NAA4	6XG01278	MULTI POSITION AIR HANDLER	TOP & BACK DENTED	\$770
2385	7	MIT	AH	MVZA24AA7	76GD0716	2T MULTI POSITION AIR HANDLER	SMALL DENT LEFT SIDE CABINET	\$1,128
222	6	MIT	AH	PEADA24AA7		2T DUCTED AIR HANDLER	PERFECT BUT OUT OF BOX	\$1,104
2861	2	MIT	AH	SLZKA09NAR1	6ZM05258	.75T CEILING CASSETTE AIR HANDLER	DAMAGED IN SOME UNKNOW MANNER	\$500
189	8	MIT	CU	MSYD30NA	6001939T	2.5T CONDENSER	BOTTOM RIGHT CORNER CRUSHED	\$799
2366	7	MIT	CU	MSZD30NA	6001562T	2.5T HP CONDENSER	SUCTION FLARE LEAKS, MANY SCRATCHES	\$817
2354	2	MIT	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT,SIDE CABINET DAMAGE	\$527
2090	2	MIT	CU	MUZFH09NA-1	74C03266	.75T HEAT PUMP CONDENSER	SIDE DENTED	\$450
2265	10	MIT	CU	MUZGE09NA2	5002801T	.75T HP COND	CORNER DENTED,PANEL WARPED	\$70
2681	2	MIT	CU	MUZGL18NA	6004961T	1.5T CONDENSER	LITTLE DENT TOP LEFT	\$741
2652	2	MIT	CU	MXZ2B20NA	6008594T	2 ZONE 1.5T HP COND	DENTED ON SIDE/SCRATCHED ON TOP	\$609
2173	8	MIT	CU	MXZ2C20NAHZ2-U1	69P03545	2 ZONE 1.5T HYPERHEAT CONDENSER	TOP & FRONT DENTED,BEEN INSTALLED	\$630
2079	6	MIT	CU	MXZ3C24NA2-U1	52U01322B	MIT 3 ZONE 2.0T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$1,110
2080	6	MIT	CU	MXZ3C30NA2-U1	54U02956C	MIT 3 ZONE 2.5T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$1,221
2266	10	MIT	CU	MXZ3C30NAHZ	4ZP01214	MIT 3 ZONE 2.5T HYPERHEAT	PANELS DENTED,POSSIBLE INTERNAL DAMAGE	\$760
2277	10	MIT	CU	MXZ3C30NAHZ-2	67P038	3 ZONE 2.5T HYPERHEAT CONDENSER	FRAME BENT,FINS BENT,SIDE DENTED	\$1,290
2801	7	MIT	CU	MXZ4C36NA2-U1	162U12009B	4 ZONE 3T HEAT PUMP CONDENSER	PORT B STRIPPED OTHERWISE PERFECT	\$1,632
2242	4	MIT	CU	MXZ4C36NAHZ	4ZU01577A	4 ZONE 3T HYPERHEAT CONDENSER	OBsolete	\$2,291
2237	4	MIT	CU	MXZ4C36NAHZ-U1	6ZU00987A	4 ZONE 3.0T HYPERHEAT	SMALL DENTS IN CABINET	\$2,068
2625	2	MIT	CU	MXZ4C36NAHZ-UI	61U01536B	4 ZONE 3T HYPERHEAT CONDENSER	COIL DAMAGED	\$2,112
2753	2	MIT	CU	MXZ4C36NH2-U1	53U01937B	4 ZONE 3T HEAT PUMP CONDENSER	MINOR SCRATCHES ON TOP	\$1,530
2273	10	MIT	CU	MXZ8C48NAHZ-U1	6XU00126A	8 ZONE 4.0T HYPERHEAT CONDENSER	COIL FINS & COIL GUARD BENT	\$2,220
2462	11	MIT	CU	PUZA36NKA7	77V01824D	3T HEAT PUMP CONDENSER	COIL FINS DENTED	\$1,440
2239	4	MIT	CU	PUZA36NKA7	77U01610D	3T HP CONDENSER	COIL FIN DAMAGE, FRONT CABINET DAMAGE	\$1,680
2699	2	MIT	CU	SUZKA12NA.TH	68P01617	MIT 1T HP CONDENSER	TOP CORNER DENTED,RIGHT PANEL BENT	\$585
2547	11	MIT	CU	SUZKA15NA	6XP01392	MIT 1.25T HP CONDENSER	SIDE CRUSHED IN	\$572
2667	12	REZ	HTR	UDAP250	BPD3062024466	REZNOR UNIT HEATER	RIGHT FRONT CORNER CRUSHED BIGLY	\$468
2675	12	TR	AH	GAM5B0B30M21EA	17173JDT1V	2.5T AIR HANDLER	SIDE OF CABINET DENTED & SCRATCHED	\$663
2665	12	TR	AH	TAM4A0A36S31ED	172132KE1V	TRANE 3T AIR HANDLER	LEFT SIDE SCRATCHED AND DENTED	\$624
2703	12	TR	AH	TAM4A0B42S31ED	172631C51V	TRANE 3.5T CONV. AIR HANDLER	RIGHT REAR CORNER DENTED	\$792
2701	12	TR	AH	TAM4A0C60S51ED	172545RM1V	TRANE 5T CONV. AIR HANDLER	OUT OF BOX,PARTIALLY INSTALLED	\$906
2544	11	TR	AH	TAM9A0A24V21DA	17201LP91V	2.0T CONV VS AIR HANDLER	BOTTOM BACK DENTED	\$752
2803	7	TR	AH	TAM9A0A24V21DA	17203Y411V	2T VS AIR HANDLER	BACK RIGHT TOP CORNER DENTED	\$951
2804	7	TR	AH	TAM9A0B30V31DA	17194KPF1V	2.5T VS AIR HANDLER	TOP RIGHT CORNER & HTR DOOR DENTED	\$975
2713	12	TR	AH	TAM9A0B30V31DA	17312NHY1V	2.5T VS AIR HANDLER	TOP OF CABINET DENTED	\$980
2674	12	TR	AH	TAM9A0C36V31DA	17204LCE1V	3T AIR HANDLER	SMALL DENT SIDE CABINET	\$835
2372	7	TR	AH	TAM9A0C36V31DA	17112PX01V	3.0T VS CONV AIR HANDLER	BACK LEFT CORNER DAMAGED	\$860
2377	7	TR	AH	TAM9A0C36V31DA	17211PP01V	3.0T VS CONV AIR HANDLER	DOWNFLOW DRAIN PAN CRACKED	\$774
2376	7	TR	AH	TAM9A0C36V31DA	172026361V	3.0T VS CONV AIR HANDLER	CABINET DENTED,DRAIN PAN CRACKED	\$731
2381	7	TR	AH	TAM9A0C36V31DA	17202BH1V	3T VS AIR HANDLER	SLIGHT DAMAGE TO CABINET	\$828
2380	7	TR	AH	TAM9A0C42V41DA	171632XU1V	3.5T VS AIR HANDLER	TOP CORNER DENTED,COIL PAN CRACKED	\$782
2174	8	TR	CL	4TXCB003DS3HCA	16424RXE5G	TRANE 1.5-2.5T HI-EFF CSD COIL	NO PRESSURE,POSSIBLE LEAK	\$105
2278	10	TR	CL	4TXCB006DS3HCAA	17205KEB5G	3.5-4.0T HI-EFF CSD COIL	CABINET SCRATCHED	\$280
2702	12	TR	CL	4TXCC007DS3HCA	172743B56G	3.5-4.0T HI-EFF CASED COIL	CABINET DENTED	\$264
2374	7	TR	CU	4TTR3024H1000A	17255J7JAF	2T CONDENSER	LEAK ON SUCTION LINE NEAR SERVICE VALVE	\$581
2671	12	TR	CU	4TTR3024H1000N	17193JLGF3F	3T CONDENSER	DRAIN PAN CHIPPED,FRONT PANEL DENTED	\$499
2362	7	TR	CU	4TTR3036H1000N	172037HT3F	TRANE 3T CONDENSER	BASE PAN DAMAGED	\$644
2363	7	TR	CU	4TTR6018J1000A	16504X10T3F	TRANE 1.5T CONDENSER	BASE PAN DAMAGED	\$702
2677	12	TR	CU	4TTR6018J1000A	17303H133F	TRANE 1.5T CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$748
2672	12	TR	CU	4TTR6024J1000B	172SSU8T3F	2T CONDENSER	DRAIN PAN CHIPPED,FRONT PANEL DENTED	\$683
2704	12	TR	CU	4TTR6042J1000A	17223LRP5F	TRANE 3.5T CONDENSER	BASE PAN CHIPPED	\$1,036
2673	12	TR	CU	4TTX6024J1000B	172746US2F	2T CONDENSER	PAN CHIPPED,PANEL DENTED	\$819
2240	4	TR	CU	4TTX8048A1000B	172538R82F	4T CONDENSER	SMALL CRACK IN BASE PAN	\$2,020
2230	4	TR	FR	TDHMB060BC3V3VB	16511N257G	95% DFLW/HORZ-R MOD FURNACE	PREVIOUSLY INSTALLED	\$1,288