

S. G. TORRICE COMPANY, INC. 03/15/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$452
2543	11	A-S	AH	GAF2A0A24S21EE	17175J351V	2T AIR HANDLER	BACK PANEL DAMAGED	\$473
2545	11	A-S	AH	GAF2A0A24S21EEA	17175J211U	2T AIR HANDLER	CORNER DENTED IN	\$452
2461	11	A-S	AH	GAF2A0A30S21E	1721MM41V	2.5T AIR HANDLER	TOP CORNER DAMAGED	\$451
2464	11	A-S	AH	GAF2A0A36S31EEA	17205LL01V	3T AIR HANDLER	SMALL DENTS BACK OF UNIT	\$455
2850	2	A-S	AH	M4AH3036B1000A	170131396M	3T AIR HANDLER	SCRAP AND A DING IN THE FRONT	\$352
2853	2	A-S	AH	M4AH3048B1000A	164260056M	4T AIR HANDLER	SMALL DENT FRONT CORNER COIL STUB BENT	\$396
2361	7	A-S	AH	TAM7A0A24H21EA	16183N0NBV	3T AIR HANDLER	BOTTOM CORNER DAMAGED	\$665
2463	11	A-S	AH	TAM7A0A24V21DAA	172250TU1V	2T AIR HANDLER	RIGHT SIDE BACK OF UNIT DENTED	\$630
142	9	A-S	AH	TAM9A0A24V21DA	17171N771V	2T VS AIR HANDLER	TOP RIGHT SIDE PUSHED IN	\$665
2382	7	A-S	AH	TAM9A0A24V21DA	17191XDA1V	2T VS AIR HANDLER	BLOWER HOUSING SAGS IN HORZ. POSITION	\$504
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED'BACK LEFT CORNER DENTED	\$672
2799	7	A-S	AH	TAM9A0A24V21DA	17395KWB1V	2T CONV. AIR HANDLER	DOOR DAMAGED/SLIGHT DENT TOP LEFT	\$836
2762	10	A-S	AH	TEM4A0B18S21SA	16393NAF2V	1.5T AIR HANDLER	DENTED,BLOWER WHEEL DAMAGED	\$245
2694	2	A-S	AH	TEM4A0B24S21SA	172421RN3V	2T AIR HANDLER	BACK RIGHT CORNER DENTED	\$315
2542	11	A-S	AH	TEM4A0B24S21SA	172636703U	2T CONV. AIR HANDLER	NO GAS IN COIL,DENTED TOP & SIDE	\$220
2695	2	A-S	AH	TEM4A0B30S31SAA	17182H1N3V	2.5T AIR HANDLER	LARGE DENT TOP REAR	\$351
2697	2	A-S	AH	TEM4A0B30S31SAA	17175APX3V	2.5T AIR HANDLER	TOP BACK LEFT CORNER CRUSHED	\$351
2482	11	A-S	AH	TEM4A0C36S41SAA	171824423V	3T AIR HANDLER	DENTED TOP & BACK,BLOWER HSG DAMAGED	\$351
2485	11	A-S	AH	TEM4A0C36S41SAA	17253YPT3V	3T AIR HANDLER	BACK TOP OF UNIT CRUSHED	\$351
2496	2	A-S	AH	TEM4A0C42S41SAA	17204JP02V	3.5T AIR HANDLER	BLOWER HOUSING DAMGED, DENTED	\$385
143	9	A-S	AH	TEM4A0C42S41SAA	172240A43V	3.5T AIR HANDLER	REAR CABINET DENTED TOP & BOTTOM	\$468
2384	7	A-S	AH	TEM4A0C42S41SAA	17295P293V	3.5T VS AIR HANDLER	BLOWER WHEEL OUT OF BALANCE/DENTED	\$504
2810	7	A-S	AH	TEM4A0C42S41SAA	17224YDD3V	3.5T AIR HANDLER	LEFT SIDE CABINET DAMAGE	\$620
2536	11	A-S	AH	TEM4A0C48S41SA	17312D313V	4T AIR HANDLER	DENTED BACK AND LEFT SIDES BOTTOM	\$484
2541	11	A-S	AH	TEM4A0C48S41SAA	17385YC3V	4T AIR HANDLER	TOP RIGHT CORNER DENTED	\$585
2761	10	A-S	AH	TEM4A0C60S51SAA	17324MMP3V	5T AIR HANDLER	MINOR DENTS IN COUPLE SPOTS	\$809
	12	A-S	CL	4MXCA001AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 24 TOTAL	\$164
	12	A-S	CL	4MXCB002AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 95 TOTAL	\$185
	12	A-S	CL	4MXCB004AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 49 TOTAL	\$205
	12	A-S	CL	4MXCB006AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 20 TOTAL	\$213
	12	A-S	CL	4MXCC005AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 21 TOTAL	\$205
	12	A-S	CL	4MXCC007AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 26 TOTAL	\$226
	12	A-S	CL	4MXCC009AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 12 TOTAL	\$246
	12	A-S	CL	4MXCD008AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 10 TOTAL	\$287
	12	A-S	CL	4MXCD010AC6HCA		3.5T-5T CONV. CASED COIL	PERFECT CONDITION 28 TOTAL	\$287

S. G. TORRICE COMPANY, INC. 03/15/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$452
188	8	A-S	CL	4TXCB004DS3HCA	17345LCE5G	3T CASED COIL	SMALL DENT BACK SIDE	\$237
2566	2	A-S	CL	4TXCB004DS3HCAA	162635NGCG	3T CASED COIL	RIGHT CORNER DENTED	\$220
2586	7	A-S	CL	4TXCB006DS3HCAA	16354JRR5G	3.5-4.0T HI-EFF CSD COIL	MINOR DAMAGE TO BACK CORNER	\$93
2371	7	A-S	CL	4TXCC009DS3HCA	16435YLHCG	5.0T HI-EFF CSD COIL	FRONT CABINET DENTED	\$317
2249	4	A-S	CL	4TXCD010DS3HCA	17305KFSCG	4-5T HI-EFF COIL	FRONT PANEL/CABINET DAMAGE	\$400
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES PUSHED IN, NOT TOO BAD	\$164
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$110
2642	2	A-S	CU	4A6V0024A1000B	1625ZH141F	2T HEAT PUMP	SIDE PANEL DENTED	\$1,612
2238	4	A-S	CU	4A6V8036A1000B	17101J1M1F	3T VS HEAT PUMP	2 PANELS SMALL DENTS/BASE CRACKED	\$1,716
2758	2	A-S	CU	4A7A3018H1000N	17164MUFAF	1.5T CONDENSER	FORKLIFT DAMAGE TO BASE	\$473
2700	2	A-S	CU	4A7A3024H1000N	173021S7AF	2T CONDENSER	SIDE PANEL DAMAGED	\$546
2093	6	A-S	CU	4A7A3024H1000N	17251648AF	2T CONDENSER	SMALL DENT BOTTOM BACK PANEL	\$533
824	6	A-S	CU	4A7A3024H1000N		2T CONDENSER	PLASTIC BASE CHIPPED	\$594
2759	2	A-S	CU	4A7A3024H1000N	17054TY8AF	2T CONDENSER	BOTTOM CORNER DENTED	\$506
2871	2	A-S	CU	4A7A3024H1000N	180933G9AF	2T CONDENSER	FRONT RIGHT CORNER DENTED	\$750
2756	2	A-S	CU	4A7A3036H1000N	173436MD3F	3T CONDENSER	BASE PANEL CHIPPED	\$704
2857	2	A-S	CU	4A7A3042E1000N	17321JU7AF	3.5T CONDENSER	SIDE PANEL VERY SLIGHTLY PUSHED IN	\$819
2386	7	A-S	CU	4A7A6030J1000A	17255MFJ5F	2.5T CONDENSER	TOP COVER,FRONT PANEL DAMAGED	\$774
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$908
2483	11	A-S	CU	4A7A7024A1000B	17304JW02F	16/17 SEER 2.0T 2S CONDENSER	TOP LEFT SIDE BADLY DENTED	\$943
2711	12	A-S	CU	4A7C3048D3000D	17323NWX3F	4.0T 208/3 CONDENSER	BASE PAN CHIPPED	\$1,118
2802	7	A-S	CU	4A7V8024A1000A	17151M5E1F	2T 18SEER CONDENSER	CHIP IN BASE PAN,LEFT PANEL DENTED	\$1,368
2851	2	A-S	CU	4MAC3018B1000H	164020156M	1.5T CONDENSER	LARGE DENT ON CORNER POST	\$396
2860	2	A-S	CU	M4AC3018B1000A	172060437M	AMERISTAR 1.5T CONDENSER	SIDE PANEL DENTED	\$460
2852	2	A-S	CU	M4AC3018B1000N	171520168M	1.5T CONDENSER	SMALL DENT TO CORNER POST	\$440
2808	7	A-S	FR	S9V2B040U3PSAAB	17326NWF3G	96% GAS FURNACE	BEEN INSTALLED,RIGHT SIDE RETURN CUT IN	\$1,000
	2	A-S	RTU	WSC060H3RJA003Q		5T PACKAGED HEAT PUMP	DEALER RETURN 4 TOTAL	\$3,040
2872	2	A-S	RTU	YHC060F1EHB000	174912165I	5T HI-EFF ROOFTOP	CORNER DENTED IN	\$3,136
	2	A-S	RTU	YHC102F3RHA25DU	173213648L	8.5T HI-EFF ROOFTOP		\$5,280
	2	A-S	RTU	YHC120F4RHA001S	154711957L	10T HI-EFF ROOFTOP		\$6,160
2870	2	A-S	RTU	YSC090F3RHA001S	173312488L	7.5T G/E ROOFTOP	LARGE SCRATCH ON SIDE PANEL	\$4,704
	2	A-S	RTU	YSC090F4RHA001S	172510628L	10T ROOFTOP		\$3,520
	2	A-S	RTU	YSC090F4RHA001S	153710669L	7.5T ROOFTOP		\$3,520
	2	A-S	RTU	YSC090F4RHA001S	150811997L	7.5T ROOFTOP		\$3,520
2367	7	MIT	AH	MSZFH06NA	7000611T	.50T WALL MOUNT HP AH	FRONT SCUFFED,MISSING REMOTE	\$215

S. G. TORRICE COMPANY, INC. 03/15/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$452
2368	7	MIT	AH	MSZFH09NA	5007022T	.75T WALL MOUNT HP	FRONT COVER & FAN BLADES BROKEN	\$156
192	8	MIT	AH	MSZFH18NA2	7008700T	1.5T HEAT PUMP AIR HANDLER	CRACK IN COVER,RIGHT SIDE	\$387
2468	11	MIT	AH	MSZGL15NA-U1	74E22485	1.25T WALL MOUNT HP	BOTTOM CRACKED	\$312
2548	11	MIT	AH	MSZGL15NA-U1	75E23645	1.25T WALL MOUNT HEAT PUMP	FRONT PANEL CRACKED,BACK MT CRUSHED	\$312
191	8	MIT	AH	MSZGL18NA-U1	3012801T	1.5T HEAT PUMP AIR HANDLER	COVER CRACKED BOTTOM RIGHT CORNER	\$344
2858	2	MIT	AH	MSZGL18NA-U1	7007381T	1.5T HP AIR HANDLER	CRACKED HOUSING	\$405
2863	2	MIT	AH	MSZGL24NA-U1	7009721T	2T HEAT PUMP AIR HANDLER	GRILL DAMAGED	\$490
2272	10	MIT	AH	MVZA18NAA4	6XG01278	MULTI POSITION AIR HANDLER	TOP & BACK DENTED	\$682
2385	7	MIT	AH	MVZA24AA7	76GD0716	2T MULTI POSITION AIR HANDLER	SMALL DENT LEFT SIDE CABINET	\$1,032
222	6	MIT	AH	PEADA24AA7		2T DUCTED AIR HANDLER	PERFECT BUT OUT OF BOX	\$1,012
2861	2	MIT	AH	SLZKA09NAR1	6ZM05258	.75T CEILING CASSETTE AIR HANDLE	DAMAGED IN SOME UNKNOW MANNER	\$460
189	8	MIT	CU	MSYD30NA	6001939T	2.5T CONDENSER	BOTTOM RIGHT CORNER CRUSHED	\$731
2366	7	MIT	CU	MSZD30NA	6001562T	2.5T HP CONDENSER	SUCTION FLARE LEAKS, MANY SCRATCHES	\$741
2354	2	MIT	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT,SIDE CABINET DAMAGE	\$473
2090	2	MIT	CU	MUZFH09NA-1	74C03266	.75T HEAT PUMP CONDENSER	SIDE DENTED	\$410
219	6	MIT	CU	MUZFH18NA2	7004275T	1.5T HYPERHEAT HP CONDENSER	SERVICE VALVE CROSS THREADED	\$943
2247	4	MIT	CU	MUZFH18NA2	7000808T	1.5T HYPERHEAT HP CONDENSER	FINS DENTED ON BACK	\$1,054
2681	2	MIT	CU	MUZGL18NA	6004961T	1.5T CONDENSER	LITTLE DENT TOP LEFT	\$665
2652	2	MIT	CU	MXZ2B20NA	6008594T	2 ZONE 1.5T HP COND	DENTED ON SIDE/SCRATCHED ON TOP	\$525
2173	8	MIT	CU	MXZ2C20NAHZ2-U1	69P03545	2 ZONE 1.5T HYPERHEAT CONDENSE	TOP & FRONT DENTED,BEEN INSTALLED	\$558
2079	6	MIT	CU	MXZ3C24NA2-U1	52U01322B	MIT 3 ZONE 2.0T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$990
2080	6	MIT	CU	MXZ3C30NA2-U1	54U02956C	MIT 3 ZONE 2.5T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$1,089
2277	10	MIT	CU	MXZ3C30NAHZ-2	67P038	3 ZONE 2.5T HYPERHEAT CONDENSE	FRAME BENT,FINS BENT,SIDE DENTED	\$1,170
2801	7	MIT	CU	MXZ4C36NA2-U1	162U12009B	4 ZONE 3T HEAT PUMP CONDENSER	PORT B STRIPPED OTHERWISE PERFECT	\$1,496
2242	4	MIT	CU	MXZ4C36NAHZ	4ZU01577A	4 ZONE 3T HYPERHEAT CONDENSER	OBSOLETE	\$2,108
2237	4	MIT	CU	MXZ4C36NAHZ-U1	6ZU00987A	4 ZONE 3.0T HYPERHEAT	SMALL DENTS IN CABINET	\$1,892
2625	2	MIT	CU	MXZ4C36NAHZ-UI	61U01536B	4 ZONE 3T HYPERHEAT CONDENSER	COIL DAMAGED	\$1,936
2753	2	MIT	CU	MXZ4C36NH2-U1	53U01937B	4 ZONE 3T HEAT PUMP CONDENSER	MINOR SCRATCHES ON TOP	\$1,394
2760	10	MIT	CU	MXZ5C42NAHZ-U1	76U01215C	5 ZONE 3.5T HYPERHEAT CONDENSE	COUPLE DENTS,MINOR FIN DAMAGE	\$2,720
2273	10	MIT	CU	MXZ8C48NAHZ-U1	6XU00126A	8 ZONE 4.0T HYPERHEAT CONDENSE	COIL FINS & COIL GUARD BENT	\$1,980
2462	11	MIT	CU	PUZA36NKA7	77V01824D	3T HEAT PUMP CONDENSER	COIL FINS DENTED	\$1,312
2239	4	MIT	CU	PUZA36NKA7	77U01610D	3T HP CONDENSER	COIL FIN DAMAGE, FRONT CABINET DAMAGE	\$1,540
2699	2	MIT	CU	SUZKA12NA.TH	68P01617	MIT. 1T HP CONDENSER	TOP CORNER DENTED,RIGHT PANEL BENT	\$533
2547	11	MIT	CU	SUZKA15NA	6XP01392	MIT 1.25T HP CONDENSER	SIDE CRUSHED IN	\$520
2667	12	REZ	HTR	UDAP250	BPD3062024466	REZNOR UNIT HEATER	RIGHT FRONT CORNER CRUSHED BIGLY	\$420

S. G. TORRICE COMPANY, INC. 03/15/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$452
2675	12	TR	AH	GAM5B0B30M21EA	17173JDT1V	2.5T AIR HANDLER	SIDE OF CABINET DENTED & SCRATCHED	\$595
2665	12	TR	AH	TAM4A0A36S31ED	172132KE1V	TRANE 3T AIR HANDLER	LEFT SIDE SCRATCHED AND DENTED	\$560
2703	12	TR	AH	TAM4A0B42S31ED	172631C51V	TRANE 3.5T CONV. AIR HANDLER	RIGHT REAR CORNER DENTED	\$720
2701	12	TR	AH	TAM4A0C60S51ED	172545RM1V	TRANE 5T CONV. AIR HANDLER	OUT OF BOX,PARTIALLY INSTALLED	\$823
2544	11	TR	AH	TAM9A0A24V21DA	17201LP91V	2.0T CONV VS AIR HANDLER	BOTTOM BACK DENTED	\$688
2803	7	TR	AH	TAM9A0A24V21DA	17203Y411V	2T VS AIR HANDLER	BACK RIGHT TOP CORNER DENTED	\$873
221	6	TR	AH	TAM9A0A24V21DA	17261JA11V	2T AIR HANDLER	TOP RIGHT CORNER CRINKLED	\$986
2809	7	TR	AH	TAM9A0A24V21DA	172878M11V	2T AIR HANDLER	WILL NEED A NEW DRAIN PAN	\$800
2804	7	TR	AH	TAM9A0B30V31DA	17194KPF1V	2.5T VS AIR HANDLER	TOP RIGHT CORNER & HTR DOOR DENTED	\$896
2713	12	TR	AH	TAM9A0B30V31DA	17312NHY1V	2.5T VS AIR HANDLER	TOP OF CABINET DENTED	\$900
2674	12	TR	AH	TAM9A0C36V31DA	17204LCE1V	3T AIR HANDLER	SMALL DENT SIDE CABINET	\$749
2372	7	TR	AH	TAM9A0C36V31DA	17112PX01V	3.0T VS CONV AIR HANDLER	BACK LEFT CORNER DAMAGED	\$780
2377	7	TR	AH	TAM9A0C36V31DA	17211PP01V	3.0T VS CONV AIR HANDLER	DOWNFLOW DRAIN PAN CRACKED	\$702
2376	7	TR	AH	TAM9A0C36V31DA	172026361V	3.0T VS CONV AIR HANDLER	CABINET DENTED,DRAIN PAN CRACKED	\$663
2381	7	TR	AH	TAM9A0C36V31DA	17202BH1V	3T VS AIR HANDLER	SLIGHT DAMAGE TO CABINET	\$756
2380	7	TR	AH	TAM9A0C42V41DA	171632XU1V	3.5T VS AIR HANDLER	TOP CORNER DENTED,COIL PAN CRACKED	\$714
2174	8	TR	CL	4TXCB003DS3HCA	16424RXE5G	TRANE 1.5-2.5T HI-EFF CSD COIL	NO PRESSURE,POSSIBLE LEAK	\$93
2702	12	TR	CL	4TXCC007DS3HCA	172743B55G	3.5-4.0T HI-EFF CASED COIL	CABINET DENTED	\$240
2374	7	TR	CU	4TTR3024H1000A	17255J7JAF	2T CONDENSER	LEAK ON SUCTION LINE NEAR SERVICE VALVE	\$527
2716	12	TR	CU	4TTR3036H1000N	1808355D3F	3T CONDENSER	BASE PAN SCRATCHED/CHIPPED	\$800
2363	7	TR	CU	4TTR6018J1000A	16504X10T3F	TRANE 1.5T CONDENSER	BASE PAN DAMAGED	\$630
2677	12	TR	CU	4TTR6018J1000A	17303H133F	TRANE 1.5T CONDENSER	BASE PAN CHIPPED,SIDE PANEL DENTED	\$680
2672	12	TR	CU	4TTR6024J1000B	172SSU8T3F	2T CONDENSER	DRAIN PAN CHIPPED,FRONT PANEL DENTED	\$613
2704	12	TR	CU	4TTR6042J1000A	17223LRP5F	TRANE 3.5T CONDENSER	BASE PAN CHIPPED	\$942
2240	4	TR	CU	4TTX8048A1000B	172538R82F	4T CONDENSER	SMALL CRACK IN BASE PAN	\$1,858
2715	12	TR	FR	S9V2C100U4PSBA	17452N7F3G	96% GAS FURNACE	BACK CABINET ALL SCRATCHED UP	\$1,316
2714	12	TR	RTU	YHC036E1EHB0000	171511608L	3T HI-EFF. ROOFTOP	PANEL SCUFFED UP,FINS PUSHED IN	\$2,331