

First Come, First Served

No Held Items

Call 1-800-888-8359

| Tag # | Br | Vndr | Type | Serial | | Description | Condition | Special |
|-------|----|-------|------|------------------|----------------|----------------------------|------------------------------------|---------|
| | | | | Model | Number | | | |
| 1007 | 2 | AQ | CL | HHU-TE-2 | 52157 | Hot Water Coil | Top flange & side dented | \$190 |
| 1090 | 2 | A-S | AC | TFM145B0FR0 | 6502G81AW | 5" Media Air Cleaner | NEW | \$25 |
| 1089 | 2 | A-S | AC | TFM145B0FR1 | 8045NKX7V | 5" Media Air Cleaner | NEW | \$25 |
| 1091 | 2 | A-S | AC | TFM145B0FR2 | 4521JDPAW | 5" Media Air Cleaner | NEW | \$25 |
| 1093 | 2 | A-S | AC | TMF210B0FR0 | 4165ET5AW | 5" Media Air Cleaner | NEW | \$25 |
| 1092 | 2 | A-S | AC | TMF210B0FR1 | 7262U417V | 5" Media Air Cleaner | NEW | \$25 |
| 1076 | 2 | A-S | AC | TFM245B0FR0 | 8223MNV7V | 5" Media Air Cleaner | NEW | \$25 |
| 1099 | 2 | A-S | AC | TFM245B0FR1 | 8203TYU7V | 5" Media Air Cleaner | NEW | \$25 |
| 1098 | 2 | A-S | AC | TFM245B0FR2 | 8203TYU7V | 5" Media Air Cleaner | NEW | \$25 |
| 1097 | 2 | A-S | AC | TFM245B0FR3 | 8085J787V | 5" Media Air Cleaner | NEW | \$25 |
| 1094 | 2 | A-S | AC | TFM260B0AH0 | 6273B01AW | 5" Media Air Cleaner | NEW | \$25 |
| 1095 | 2 | A-S | AC | TFM260B0AH1 | 4263LRHAW | 5" Media Air Cleaner | NEW | \$25 |
| 1096 | 2 | A-S | AC | TFM260B0AH2 | 4451BS6AW | 5" Media Air Cleaner | NEW | \$25 |
| 84 | 2 | A-S | AH | 4TEC3F24B1000A | 102642241V | 2 Ton A/H | Blower wheel & cabinet damaged | \$125 |
| 87 | 2 | A-S | AH | 4TEC3F24B1000A | 10473RD01V | 2 Ton A/H | Blower wheel & cabinet damaged | \$340 |
| 90 | 2 | A-S | AH | 4TEC3F60B1000A | 1113381Y1V | 5 Ton A/H | Blower wheel & cabinet damaged | \$612 |
| 1022 | 2 | A-S | AH | TWE060A300E | 7182KYBD | 5 Ton A/H | Out of box | \$630 |
| 1008 | 2 | A-S | AH | AAM7A0A24H21SA | 11035KNA2V | 2 Ton A/H | Dents | \$760 |
| 898 | 11 | A-S | AH | AAM7A0A24H21SA | 11313YNK2V | 2 Ton A/H | Back cabinet dented | \$836 |
| 1080 | 2 | A-S | AH | AAM7A0C36H31SA | 11401UEH2V | 3 Ton A/H | Back of unit scratched & dented | \$989 |
| 1061 | 2 | A-S | AH | TWE120D300A | 10051PCXBD | 10 Ton Condenser | Side panel smashed in | \$1,507 |
| 892 | 2 | A-S | CL | 4TXCB036BC3HCB | 11413KA95G | 3 Ton Cased Coil | Sides crushed | \$216 |
| 705 | 2 | A-S | CU | TTA240B300F | 82257N61F | 20 Ton Cond. | Dents | \$187 |
| 531 | 2 | A-S | CU | 4A6Z0036A1000B | 9391K491F | 3 Ton Cond. | Defective coil & dents | \$468 |
| 878 | 2 | A-S | CU | 4A7A5048E1000A | 10321ODU2F | 4 Ton Cond. | Back & bottom damage | \$1,036 |
| 1002 | 2 | A-S | CU | 4A7C3036A4000B | 111024BK3F | 3 Ton Cond. | Installed - never started | \$740 |
| 805 | 2 | A-S | CU | 2A7A3036A1000A | 9322WU43F | 3 Ton Cond. | Bad coil | \$570 |
| 1012 | 2 | A-S | CU | 4A7A5042E1000A | 11252KH72F | 3.5 Ton Cond. | Installed - never started | \$1,128 |
| 1013 | 2 | A-S | CU | 4A7C3036A4000B | 11261PS13F | 3 Ton Cond. | Out of box | \$902 |
| 815 | 2 | A-S | CU | 4A7A3024D1000A | 10201NDL3F | 2.5 Ton Cond. | Dirty/Missing service access panel | \$865 |
| 1003 | 2 | A-S | CU | 4A7A3036D1000A | 1114426B3F | 3 Ton Cond. | Coil pushed in | \$897 |
| 1014 | 2 | A-S | CU | 4A7A6048A1000A | 11201PXE2F | 4 Ton Cond. | Bottom front of coil pushed in | \$1,681 |
| 1015 | 2 | A-S | CU | TTA090D300A | 10404D1DYA | 7.5 Ton Cond. | Out of box/Some fins bent | \$1,965 |
| 1017 | 2 | A-S | CU | 4A6H3018A1000B | 11013L684F | 1.5 Ton HP Cond | Out of box/Perfect | \$1,060 |
| 1078 | 2 | A-S | CU | 2A7B3036NITRO | 11132LXJ3F | 3 Ton Cond R22 | Side panels smashed in | \$844 |
| 1079 | 2 | A-S | CU | 2A7B3036NITRO | 11132LLM3F | 3 Ton Cond R22 | Side panels badly dented | \$844 |
| 1075 | 2 | A-S | CU | TTA120C300G | 737208DAD | 10 Ton Cond. | Fan shroud damaged mult. Dents | \$1,880 |
| 895 | 11 | A-S | CU | 4A6H5042E1000A | 11402L432F | 3.5 Ton Heat Pump | Side crushed,coil damaged | \$672 |
| 894 | 11 | A-S | CU | 4A7A5030E1000A | 11424R2P2F | 2.5 Ton Cond. | Back of unit crushed | \$672 |
| 874 | 11 | A-S | FR | AUH2B080A9V4VA | 11244P607G | 95% Gas Furnace | Back bottom/top dented | \$1,218 |
| 1052 | 2 | A-S | FR | TLF1M087A9V5VA | 11982230X | Variable Speed Oil Furnace | Bottom right side pushed in | \$1,589 |
| 33 | 4 | A-S | FR | AUD1A040A9241A | 11241XH21G | 80% Gas Furnace | Installed w/LP kit | \$432 |
| 1083 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000731 | 5 Ton Cased Coil | New | \$54 |
| 1084 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000727 | 5 Ton Cased Coil | New | \$54 |
| 1088 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000728 | 5 Ton Cased Coil | New | \$54 |
| 1086 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000726 | 5 Ton Cased Coil | New | \$54 |
| 1087 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000733 | 5 Ton Cased Coil | New | \$54 |
| 1082 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000729 | 5 Ton Cased Coil | New | \$54 |
| 1085 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000730 | 5 Ton Cased Coil | New | \$54 |
| 1081 | 2 | ASPEN | CL | CC60E44-245L-036 | E09-00000732 | 5 Ton Cased Coil | New | \$54 |
| 1004 | 2 | ASPEN | CL | CE36D44-175L-015 | C09-00007962 | 3 Ton Cased Coil | Back panel dented | \$237 |
| 1019 | 2 | BARD | HP | PH1224-1 | A041880635 | Bard Ht Pump | Ancient, still in box | \$172 |
| 1020 | 2 | BARD | HTR | EH3PC-A10 | J041938828 | Bard 10KW htr | In box,old & unwanted | \$31 |
| 1059 | 2 | BRKO | HTR | CUH93502203FFB | | Cab Htr 208V/3Ph/2KW | Perfect,still in box | \$480 |
| 1051 | 2 | BRKO | HTR | CUH93502203FFB | | Cab Htr 208V/3Ph/2KW | Perfect,still in box | \$480 |
| 1053 | 2 | CA | AH | AHG30-0A | R1005090060 | 2.5 Ton Hydro AH | Small dent on back of unit | \$522 |
| 883 | 11 | CA | CU | RSE48S | 30915503115284 | 4 Ton Cond. | Panel crushed/coil dented | \$736 |
| 578 | 2 | MIT | AH | MSYA24NA | | 2 Ton A/H | Out of box | \$252 |

First Come, First Served

No Held Items

Call 1-800-888-8359

Serial

| | | | | | | | | |
|------|---|------|----|--------------|-----------|--------------------|-------------------------------------|---------|
| 265 | 3 | MITS | AH | MSYA15NA | | 1.25 Ton A/H | NEW | \$188 |
| 266 | 3 | MITS | AH | MSYA15NA | | 1.25 Ton A/H | NEW | \$188 |
| 267 | 3 | MITS | AH | MSYA15NA | | 1.25 Ton A/H | NEW | \$188 |
| 268 | 3 | MITS | AH | MSYA15NA | | 1.25 Ton A/H | NEW | \$188 |
| 1071 | 3 | MITS | AH | MSZA09NA | 000664T | .75 Ton A/H | NEW | \$166 |
| 264 | 3 | MITS | AH | PKAA30FAL | | 2.5 Ton A/H | NEW | \$390 |
| 258 | 3 | MITS | AH | PKAA30FAL | | 2.5 Ton A/H | NEW | \$390 |
| 259 | 3 | MITS | AH | PKAA30FAL | | 2.5 Ton A/H | NEW | \$390 |
| 260 | 3 | MITS | AH | PKAA30FAL | | 2.5 Ton A/H | NEW | \$390 |
| 262 | 3 | MITS | AH | PLAA30AA | | 2.5 Ton A/H | NEW | \$614 |
| 257 | 3 | MITS | AH | PKAA12GAL | | 1.0 Ton A/H | NEW | \$221 |
| 808 | 2 | MITS | AH | MSZ-A09NA | 6010168T | .75 Ton A/H | Coil dented | \$272 |
| 809 | 2 | MITS | AH | PKAA24KA4 | 0XNL00196 | 2 Ton A/H | Coil leaks | \$442 |
| 816 | 2 | MITS | AH | MSYGE18NA | 9000169 | 1.5 Ton A/H | Minor scatches | \$385 |
| 875 | 2 | MITS | AH | MSZGE09NA | 1009394T | .75 Ton A/H | Corners dented | \$246 |
| 518 | 2 | MITS | CU | MUYGE15NA | 0000940T | 1.3 Ton Cond | Front panel dented | \$195 |
| 522 | 2 | MITS | CU | PUYA30NHA3 | 91U00485B | 2.5 Ton Cond. | Small dents | \$600 |
| 616 | 2 | MITS | CU | MUY-GE15NA | 0000663T | 1.3 Ton Cond | Dented panels | \$243 |
| 618 | 2 | MITS | CU | MUZ-FE09NA | 90001668T | .75 Ton Cond. | Crushed | \$198 |
| 619 | 2 | MITS | CU | PUMY-P48NMHU | 97U0014OD | 4 Ton Cond. | Leaky coil | \$1,008 |
| 577 | 2 | MITS | CU | PUZA42NHA3 | 72U00194B | 3.5 Ton Cond. | Out of box | \$1,260 |
| 576 | 2 | MITS | CU | MUZGE12NA | 0004051T | 1 Ton Cond. | Coil dents & fins bent | \$249 |
| 590 | 2 | MITS | CU | MUZGE12NA | 0003432T | 1 Ton Cond. | Side of unit dented | \$325 |
| 1074 | 3 | MITS | CU | MUZFD09NA | 8001881T | .75 Ton Cond. | NEW | \$231 |
| 269 | 3 | MITS | CU | MUZFD09NA | | .75 Ton Cond. | NEW | \$231 |
| 270 | 3 | MITS | CU | MUZFD09NA | | .75 Ton Cond. | NEW | \$231 |
| 271 | 3 | MITS | CU | MUZFD09NA | | .75 Ton Cond. | NEW | \$231 |
| 272 | 3 | MITS | CU | MUZFD09NA | | .75 Ton Cond. | NEW | \$231 |
| 273 | 3 | MITS | CU | MUZFD09NA | | .75 Ton Cond. | NEW | \$231 |
| 299 | 3 | MITS | CU | MUZA12NA | | 1.0 Ton Cond. | NEW | \$218 |
| 256 | 3 | MITS | CU | MUZA24NA | | 2 Ton Cond. | NEW | \$317 |
| 297 | 3 | MITS | CU | MUZA15NA | | 1.25 Ton Cond. | NEW | \$251 |
| 298 | 3 | MITS | CU | MUZA15NA | | 1.25 Ton Cond. | NEW | \$251 |
| 293 | 3 | MITS | CU | MUZA17NA | | 1.75 Ton Cond. | NEW | \$294 |
| 294 | 3 | MITS | CU | MUZA17NA | | 1.75 Ton Cond. | NEW | \$294 |
| 295 | 3 | MITS | CU | MUZA17NA | | 1.75 Ton Cond. | NEW | \$294 |
| 296 | 3 | MITS | CU | MUZA17NA | | 1.75 Ton Cond. | NEW | \$294 |
| 263 | 3 | MITS | CU | PCAA30GA | | 2.5 Ton A/H | NEW | \$440 |
| 261 | 3 | MITS | CU | PCAA30GA | | 2.5 Ton A/H | NEW | \$440 |
| 254 | 3 | MITS | CU | PUZA36NHA | | 3 Ton Cond. | NEW | \$913 |
| 255 | 3 | MITS | CU | PUZA36NHA | | 3 Ton Cond. | NEW | \$913 |
| 636 | 2 | MITS | CU | MUZFE12WA | 0002031T | 1 Ton Cond. | Outside casing damaged | \$407 |
| 637 | 2 | MITS | CU | MUZFE09NA | 9001485T | .75 Ton Cond. | Outside casing damaged | \$330 |
| 804 | 2 | MITS | CU | MUZ-FE09NA | 9000501T | .75 Ton Cond. | Dented panels | \$476 |
| 879 | 2 | MITS | CU | MUYGE15NA | 0003861T | 1.25 Ton Cond. | Fan side bottom crushed | \$441 |
| 813 | 2 | MITS | CU | PUMY-P36NHMU | 01U00342B | 3 Ton Cond. | Dented service panels - coil damage | \$1,470 |
| 811 | 2 | MITS | CU | MUZGE12NA | 1003915T | 1 Ton Cond. | Base pan & legs bent | \$532 |
| 1055 | 4 | MITS | CU | MXZ4B36NA | 12902919C | Quad Zone HP Cond. | Right side top & back dented | \$1,844 |
| 1058 | 2 | MITS | CU | MUYD36NA | 1001739T | 3 Ton Condenser | Top & front panel minor dents | \$1,615 |