

S. G. TORRICE COMPANY, INC. 05/17/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$409.50
2543	11	A-S	AH	GAF2A0A24S21EE	17175J351V	2T AIR HANDLER	BACK PANEL DAMAGED	\$429.00
2545	11	A-S	AH	GAF2A0A24S21EEA	17175J211U	2T AIR HANDLER	CORNER DENTED IN	\$409.50
2461	11	A-S	AH	GAF2A0A30S21E	1721MM41V	2.5T AIR HANDLER	TOP CORNER DAMAGED	\$407.00
2464	11	A-S	AH	GAF2A0A36S31EEA	17205LL01V	3T AIR HANDLER	SMALL DENTS BACK OF UNIT	\$403.00
2876	2	A-S	AH	M4AH3024B1000A	141530127M	2T AIR HANDLER	DENTED ON TOP & RIGHT SIDE	\$294.00
2850	2	A-S	AH	M4AH3036B1000A	170131396M	3T AIR HANDLER	SCRAP AND A DING IN THE FRONT	\$312.00
2853	2	A-S	AH	M4AH3048B1000A	164260056M	4T AIR HANDLER	SMALL DENT FRONT CORNER COIL STUB BENT	\$351.00
2361	7	A-S	AH	TAM7A0A24H21EA	16183N0NBV	3T AIR HANDLER	BOTTOM CORNER DAMAGED	\$589.00
2463	11	A-S	AH	TAM7A0A24V21DAA	172250TU1V	2T AIR HANDLER	RIGHT SIDE BACK OF UNIT DENTED	\$558.00
142	9	A-S	AH	TAM9A0A24V21DA	17171N771V	2T VS AIR HANDLER	TOP RIGHT SIDE PUSHED IN	\$589.00
2382	7	A-S	AH	TAM9A0A24V21DA	17191XDA1V	2T VS AIR HANDLER	BLOWER HOUSING SAGS IN HORZ. POSITION	\$456.00
2383	7	A-S	AH	TAM9A0A24V21DA	17191WR31V	2T VS AIR HANDLER	DOOR CRACKED'BACK LEFT CORNER DENTED	\$608.00
2799	7	A-S	AH	TAM9A0A24V21DA	17395KWB1V	2T CONV. AIR HANDLER	DOOR DAMAGED/SLIGHT DENT TOP LEFT	\$741.00
2762	10	A-S	AH	TEM4A0B18S21SA	16393NAF2V	1.5T AIR HANDLER	DENTED,BLOWER WHEEL DAMAGED	\$215.00
2694	2	A-S	AH	TEM4A0B24S21SA	172421RN3V	2T AIR HANDLER	BACK RIGHT CORNER DENTED	\$279.00
2542	11	A-S	AH	TEM4A0B24S21SA	172636703U	2T CONV. AIR HANDLER	NO GAS IN COIL,DENTED TOP & SIDE	\$195.00
2697	2	A-S	AH	TEM4A0B30S31SAA	17175APX3V	2.5T AIR HANDLER	TOP BACK LEFT CORNER CRUSHED	\$315.00
2482	11	A-S	AH	TEM4A0C36S41SAA	171824423V	3T AIR HANDLER	DENTED TOP & BACK,BLOWER HSG DAMAGED	\$315.00
2485	11	A-S	AH	TEM4A0C36S41SAA	17253YPT3V	3T AIR HANDLER	BACK TOP OF UNIT CRUSHED	\$315.00
2496	2	A-S	AH	TEM4A0C42S41SAA	17204JP02V	3.5T AIR HANDLER	BLOWER HOUSING DAMGED, DENTED	\$341.00
143	9	A-S	AH	TEM4A0C42S41SAA	172240A43V	3.5T AIR HANDLER	REAR CABINET DENTED TOP & BOTTOM	\$420.00
2384	7	A-S	AH	TEM4A0C42S41SAA	17295P293V	3.5T VS AIR HANDLER	BLOWER WHEEL OUT OF BALANCE/DENTED	\$456.00
820	6	A-S	AH	TEM4A0C42S41SAA	1810418G3V	3.5T AIR HANDLER	BLOWER HOUSING WARPED	\$500.00
2536	11	A-S	AH	TEM4A0C48S41SA	17312D313V	4T AIR HANDLER	DENTED BACK AND LEFT SIDES BOTTOM	\$429.00
2541	11	A-S	AH	TEM4A0C48S41SAA	17385YC3V	4T AIR HANDLER	TOP RIGHT CORNER DENTED	\$533.00
2761	10	A-S	AH	TEM4A0C60S51SAA	17324MMP3V	5T AIR HANDLER	MINOR DENTS IN COUPLE SPOTS	\$709.50
	12	A-S	CL	4MXCA001AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 16 TOTAL	\$148.00
	12	A-S	CL	4MXCB002AC6HCA		1.5T-2.5T CONV. CASED COIL	PERFECT CONDITION 87 TOTAL	\$166.50
	12	A-S	CL	4MXCB004AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 43 TOTAL	\$185.00
	12	A-S	CL	4MXCB006AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 19 TOTAL	\$192.40
	12	A-S	CL	4MXCC005AC6HCA		2.5T-3T CONV. CASED COIL	PERFECT CONDITION 21 TOTAL	\$185.00
	12	A-S	CL	4MXCC007AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 26 TOTAL	\$203.50
	12	A-S	CL	4MXCC009AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 12 TOTAL	\$222.00
	12	A-S	CL	4MXCD008AC6HCA		3.5T-4T CONV. CASED COIL	PERFECT CONDITION 9 TOTAL	\$259.00
	12	A-S	CL	4MXCD010AC6HCA		3.5T-5T CONV. CASED COIL	PERFECT CONDITION 26 TOTAL	\$259.00

S. G. TORRICE COMPANY, INC. 05/17/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$409.50
2566	2	A-S	CL	4TXCB004DS3HCAA	162635NGCG	3T CASED COIL	RIGHT CORNER DENTED	\$195.00
2814	7	A-S	CL	4TXCC007DS3HCA	17121H6R5G	3.5-4T COIL	NEEDS NEW TXV	\$332.22
2371	7	A-S	CL	4TXCC009DS3HCA	16435YLHCG	5.0T HI-EFF CSD COIL	FRONT CABINET DENTED	\$284.20
2249	4	A-S	CL	4TXCD010DS3HCA	17305KFSCG	4-5T HI-EFF COIL	FRONT PANEL/CABINET DAMAGE	\$365.50
179	2	A-S	CL	4TXCD010DS3HCA	17514X45CG	4-5T COIL	BACK AND RIGHT SIDE CRUSHED	\$294.00
121	2	A-S	CL	4TXCD061BC3HCC	1526302ECG	5T COIL	2 SIDES PUSHED IN, NOT TOO BAD	\$148.00
2049	2	A-S	CL	4TXCD064BC3HCB	1345N315G	5T COIL	OUT OF BOX,SLIGHT DENTS,DIRTY	\$80.30
2238	4	A-S	CU	4A6V8036A1000B	17101J1M1F	3T VS HEAT PUMP	2 PANELS SMALL DENTS/BASE CRACKED	#####
2857	2	A-S	CU	4A7A3042E1000N	17321JU7AF	3.5T CONDENSER	SIDE PANEL VERY SLIGHTLY PUSHED IN	\$747.60
2764	10	A-S	CU	4A7A3042E1000N	17084KDhaf	3.5T CONDENSER	BASE PAN CRACKED	\$878.08
2359	7	A-S	CU	4A7A7024A1000B	17082YY02F	16/17 SEER 2T CONDENSER	PLASTIC BASE CRACKED	\$742.50
2483	11	A-S	CU	4A7A7024A1000B	17304JW02F	16/17 SEER 2.0T 2S CONDENSER	TOP LEFT SIDE BADLY DENTED	\$851.00
2711	12	A-S	CU	4A7C3048D3000D	17323NWG3F	4.0T 208/3 CONDENSER	BASE PAN CHIPPED	#####
2851	2	A-S	CU	4MAC3018B1000H	164020156M	1.5T CONDENSER	LARGE DENT ON CORNER POST	\$351.00
2860	2	A-S	CU	M4AC3018B1000A	172060437M	AMERISTAR 1.5T CONDENSER	SIDE PANEL DENTED	\$420.00
2852	2	A-S	CU	M4AC3018B1000N	171520168M	1.5T CONDENSER	SMALL DENT TO CORNER POST	\$390.00
2875	2	A-S	CU	M4AC3018B1000NA	173130189M	1.5T CONDENSER	SLIGHT DENT BOTTOM BACK LEFT	\$490.00
2722	12	A-S	CU	TTA120H300A	17273LT5YA	10T CONDENSER	BRAND NEW OUT OF BOX	#####
2865	2	A-S	FR	AUC1B060A9361A	181145RD2G	92% GAS FURNACE	TOP DOOR/BACK CORNER DENTED	\$648.60
2864	2	A-S	FR	AUC1B080A9421A	17473TJ62G	92% GAS FURNACE	SIDE PANEL DENTED	\$691.20
2808	7	A-S	FR	S9V2B040U3PSAAB	17326NWF3G	96% GAS FURNACE	BEEN INSTALLED,RIGHT SIDE RETURN CUT IN	\$920.00
2811	7	A-S	FR	S9V2C100U4PSBA	17252SRT3G	96% GAS FURNACE	WAS INSTALLED, RUNS FINE	#####
194	2	A-S	FR	S9V2C100U4VSAA	18083PTG3G	97% GAS FURNACE	DENTED ON RIGHT,TOP AND BOTTOM	\$490.00
	2	A-S	RTU	WSC060H3RJA003Q		5T PACKAGED HEAT PUMP	DEALER RETURN 3 TOTAL	#####
2872	2	A-S	RTU	YHC060F1EHB0000	174912165I	5T HI-EFF ROOFTOP	CORNER DENTED IN	#####
	2	A-S	RTU	YSC090F4RHA001S	172510628L	7.5T ROOFTOP	INSTALLED,RETURNED BY CUSTOMER	#####
	2	A-S	RTU	YSC090F4RHA001S	153710669L	7.5T ROOFTOP	OUT OF CRATE,DAMAGED,SCRATCHED	#####
	2	A-S	RTU	YSC090F4RHA001S	150811997L	7.5T ROOFTOP	OUT OF CRATE,DAMAGED,SCRATCHED	#####
193	2	FIRST	AH	48HBXB-HW-R410	6048H3HW4X	FIRST CO 4T AIR HANDLER	LEFT SIDE & FRONT DENTED	\$784.00
2367	7	MIT	AH	MSZFH06NA	7000611T	.50T WALL MOUNT HP AH	FRONT SCUFFED,MISSING REMOTE	\$192.50
2368	7	MIT	AH	MSZFH09NA	5007022T	.75T WALL MOUNT HP	FRONT COVER & FAN BLADES BROKEN	\$140.00
2468	11	MIT	AH	MSZGL15NA-U1	74E22485	1.25T WALL MOUNT HP	BOTTOM CRACKED	\$280.00
2548	11	MIT	AH	MSZGL15NA-U1	75E23645	1.25T WALL MOUNT HEAT PUMP	FRONT PANEL CRACKED,BACK MT CRUSHED	\$280.00
2858	2	MIT	AH	MSZGL18NA-U1	7007381T	1.5T HP AIR HANDLER	CRACKED HOUSING	\$369.00
2863	2	MIT	AH	MSZGL24NA-U1	7009721T	2T HEAT PUMP AIR HANDLER	GRILL DAMAGED	\$430.00

S. G. TORRICE COMPANY, INC. 05/17/2018

Pricing/Products Available For Purchase By Licensed HVAC Contrator Only*

** Must have a current account with the S. G. Torrice Company*

First Come, First Served - No Held Items - Call 1-800-888-8359

Tag #	Br	Vndr	Type	Model	Serial Number	Description	Condition	Special
2540	11	A-S	AH	GAF2A0A18S11EEA	17202TX71V	1.5T AIR HANDLER	SMALL DENT LEFT SIDE	\$409.50
2385	7	MIT	AH	MVZA24AA7	76GD0716	2T MULTI POSITION AIR HANDLER	SMALL DENT LEFT SIDE CABINET	\$936.00
222	6	MIT	AH	PEADA24AA7		2T DUCTED AIR HANDLER	PERFECT BUT OUT OF BOX	\$897.00
189	8	MIT	CU	MSYD30NA	6001939T	2.5T CONDENSER	BOTTOM RIGHT CORNER CRUSHED	\$663.00
2366	7	MIT	CU	MSZD30NA	6001562T	2.5T HP CONDENSER	SUCTION FLARE LEAKS, MANY SCRATCHES	\$665.00
2354	2	MIT	CU	MUZFH09NA	4006167T	.75T HEAT PUMP CONDENSER	FEET BENT,SIDE CABINET DAMAGE	\$418.50
2090	2	MIT	CU	MUZFH09NA-1	74C03266	.75T HEAT PUMP CONDENSER	SIDE DENTED	\$370.00
219	6	MIT	CU	MUZFH18NA2	7004275T	1.5T HYPERHEAT HP CONDENSER	SERVICE VALVE CROSS THREADED	\$861.00
2247	4	MIT	CU	MUZFH18NA2	7000808T	1.5T HYPERHEAT HP CONDENSER	FINS DENTED ON BACK	\$924.50
2681	2	MIT	CU	MUZGL18NA	6004961T	1.5T CONDENSER	LITTLE DENT TOP LEFT	\$589.00
2652	2	MIT	CU	MXZ2B20NA	6008594T	2 ZONE 1.5T HP COND	DENTED ON SIDE/SCRATCHED ON TOP	\$231.00
2173	8	MIT	CU	MXZ2C20NAHZ2-U1	69P03545	2 ZONE 1.5T HYPERHEAT CONDENSE	TOP & FRONT DENTED,BEEN INSTALLED	\$486.00
2867	2	MIT	CU	MXZ2C20NAHZ2-U1	7VP04323	2 ZONE 1.5T HYPERHEAT CONDENSE	DENTED/COIL DAMAGED	#####
2079	6	MIT	CU	MXZ3C24NA2-U1	52U01322B	MIT 3 ZONE 2.0T HP CONDENSER	OUT OF BOX,SLIGHTLY SCUFFED	\$810.00
2277	10	MIT	CU	MXZ3C30NAHZ-2	67P038	3 ZONE 2.5T HYPERHEAT CONDENSE	FRAME BENT,FINS BENT,SIDE DENTED	#####
2242	4	MIT	CU	MXZ4C36NAHZ	4ZU01577A	4 ZONE 3T HYPERHEAT CONDENSER	OBSOLETE	#####
2237	4	MIT	CU	MXZ4C36NAHZ-U1	6ZU00987A	4 ZONE 3.0T HYPERHEAT	SMALL DENTS IN CABINET	#####
2753	2	MIT	CU	MXZ4C36NH2-U1	53U01937B	4 ZONE 3T HEAT PUMP CONDENSER	MINOR SCRATCHES ON TOP	#####
2760	10	MIT	CU	MXZ5C42NAHZ-U1	76U01215C	5 ZONE 3.5T HYPERHEAT CONDENSE	COUPLE DENTS,MINOR FIN DAMAGE	#####
2273	10	MIT	CU	MXZ8C48NAHZ-U1	6XU00126A	8 ZONE 4.0T HYPERHEAT CONDENSE	COIL FINS & COIL GUARD BENT	#####
2462	11	MIT	CU	PUZA36NKA7	77V01824D	3T HEAT PUMP CONDENSER	COIL FINS DENTED	#####
2239	4	MIT	CU	PUZA36NKA7	77U01610D	3T HP CONDENSER	COIL FIN DAMAGE, FRONT CABINET DAMAGE	#####
2699	2	MIT	CU	SUZKA12NA.TH	68P01617	MIT. 1T HP CONDENSER	TOP CORNER DENTED,RIGHT PANEL BENT	\$481.00
2547	11	MIT	CU	SUZKA15NA	6XP01392	MIT 1.25T HP CONDENSER	SIDE CRUSHED IN	\$468.00
2667	12	REZ	HTR	UDAP250	BPD3062024466	REZNOR UNIT HEATER	RIGHT FRONT CORNER CRUSHED BIGLY	\$372.00
2675	12	TR	AH	GAM5B0B30M21EA	17173JDT1V	2.5T AIR HANDLER	SIDE OF CABINET DENTED & SCRATCHED	\$527.00
2665	12	TR	AH	TAM4A0A36S31ED	172132KE1V	TRANE 3T AIR HANDLER	LEFT SIDE SCRATCHED AND DENTED	\$496.00
2703	12	TR	AH	TAM4A0B42S31ED	172631C51V	TRANE 3.5T CONV. AIR HANDLER	RIGHT REAR CORNER DENTED	\$648.00
2701	12	TR	AH	TAM4A0C60S51ED	172545RM1V	TRANE 5T CONV. AIR HANDLER	OUT OF BOX,PARTIALLY INSTALLED	\$740.88
2544	11	TR	AH	TAM9A0A24V21DA	17201LP91V	2.0T CONV VS AIR HANDLER	BOTTOM BACK DENTED	\$624.00
2804	7	TR	AH	TAM9A0B30V31DA	17194KPF1V	2.5T VS AIR HANDLER	TOP RIGHT CORNER & HTR DOOR DENTED	\$815.90
2713	12	TR	AH	TAM9A0B30V31DA	17312NHY1V	2.5T VS AIR HANDLER	TOP OF CABINET DENTED	\$820.00
2674	12	TR	AH	TAM9A0C36V31DA	17204LCE1V	3T AIR HANDLER	SMALL DENT SIDE CABINET	\$663.40
2377	7	TR	AH	TAM9A0C36V31DA	17211PP01V	3.0T VS CONV AIR HANDLER	DOWNFLOW DRAIN PAN CRACKED	\$630.00
2376	7	TR	AH	TAM9A0C36V31DA	172026361V	3.0T VS CONV AIR HANDLER	CABINET DENTED,DRAIN PAN CRACKED	\$595.00
2381	7	TR	AH	TAM9A0C36V31DA	17202BH1V	3T VS AIR HANDLER	SLIGHT DAMAGE TO CABINET	\$684.00

